

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M000783

DATE: 29-Aug-2014

## PRODUCT DISCONTINUANCE NOTICE

| Notice Type    | Maxim Part Number | Recommeded Replacement | Last Order Date | Last Delivery Date | Reason                                     |
|----------------|-------------------|------------------------|-----------------|--------------------|--|
| Discontinuance | MAX3872EVKIT      | MAX3872EVKIT#          | 29-Aug-2014     | 28-Aug-2016        | The eval kit is no longer supported        |
| Discontinuance | MX7572BQ12        | N/A                    | 02-Mar-2015     | 28-Aug-2016        | Part can no longer be manufactured         |
| Discontinuance | MAX1238EVKIT      | N/A                    | 29-Aug-2014     | 28-Aug-2016        | The eval kit is no longer supported        |
| Discontinuance | MAX11642EEG       | N/A                    | 29-Aug-2014     | 28-Aug-2016        | The part was not released                  |
| Discontinuance | MAX11641EEG       | N/A                    | 29-Aug-2014     | 28-Aug-2016        | The part was not released                  |
| Discontinuance | MAX11633EEG       | N/A                    | 29-Aug-2014     | 28-Aug-2016        | The part was not released                  |
| Discontinuance | MAX11631EEG       | N/A                    | 29-Aug-2014     | 28-Aug-2016        | The part was not released                  |
| Discontinuance | MAX11630EEG       | N/A                    | 29-Aug-2014     | 28-Aug-2016        | The part was not released                  |
| Discontinuance | MAX11625EEG       | N/A                    | 29-Aug-2014     | 28-Aug-2016        | The part was not released                  |
| Discontinuance | MAX11623EEG       | N/A                    | 29-Aug-2014     | 28-Aug-2016        | The part was not released                  |
| Discontinuance | LMX339HAUD+T      | MAX9095AUD+T           | 31-Aug-2015     | 28-Aug-2016        | Part can no longer be manufactured         |
| Discontinuance | MAX9154EUI+       | N/A                    | 02-Mar-2015     | 28-Aug-2016        | Part can no longer be manufactured         |
| Discontinuance | MAX1781ETM+       | MAX17817ETI+T          | 31-Aug-2015     | 28-Aug-2016        | Part no longer meets customer requirements |
| Discontinuance | MAX1781ETM+T      | MAX17817ETI+T          | 31-Aug-2015     | 28-Aug-2016        | Part no longer meets customer requirements |
| Discontinuance | PHY1095-01DS+GR   | N/A                    | 29-Aug-2014     | 28-Aug-2016        | The part was not released                  |
| Discontinuance | PHY1097-03DS+GR   | N/A                    | 02-Mar-2015     | 28-Aug-2016        | The part was not released                  |
| Discontinuance | PHY1090-DS+GR     | N/A                    | 29-Aug-2014     | 28-Aug-2016        | The part was not released                  |
| Discontinuance | MAX4206EVKIT      | MAX4206EVKIT+          | 29-Aug-2014     | 28-Aug-2016        | The eval kit is no longer supported        |
| Discontinuance | DS1804-010        | N/A                    | 29-Aug-2014     | 28-Aug-2016        | Part can no longer be manufactured         |
| Discontinuance | MAX1810ESA+T      | MAX8869EUE10+T         | 02-Mar-2015     | 28-Aug-2016        | Part can no longer be manufactured         |
| Discontinuance | MAX98090EVKIT#    | MAX98090EVKIT#TQFN     | 29-Aug-2014     | 28-Aug-2016        | The eval kit is no longer supported        |
| Discontinuance | MAX1518EVKIT+     | MAX1518EVKIT           | 29-Aug-2014     | 28-Aug-2016        | The eval kit is no longer supported        |
| Discontinuance | MAX4230AXK+C7W    | MAX4230AXK+T           | 02-Mar-2015     | 28-Aug-2016        | Part can no longer be manufactured         |
| Discontinuance | DS3905U-020+      | N/A                    | 02-Mar-2015     | 28-Aug-2016        | Part can no longer be manufactured         |
| Discontinuance | LMX331AUK+T       | MAX9647AUK+T           | 31-Aug-2015     | 28-Aug-2016        | Part can no longer be manufactured         |
| Discontinuance | LMX331AUK+C7Z     | MAX9647AUK+T           | 31-Aug-2015     | 28-Aug-2016        | Part can no longer be manufactured         |

| Discontinuance | LMX331AXK+T      | MAX9648AXK+T      | 31-Aug-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
|----------------|------------------|-------------------|-------------|-------------|--|
| Discontinuance | LMX331HAUK+T     | MAX9647AUK+T      | 31-Aug-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | LMX331HAXK+      | MAX9648AXK+T      | 31-Aug-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | LMX339ASD+       | MAX9094ASD+       | 31-Aug-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | LMX339AUD+       | MAX9095AUD+       | 31-Aug-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | LMX339HASD+      | MAX9094ASD+       | 31-Aug-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | LMX339HAUD+      | MAX9095AUD+       | 31-Aug-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAX3945AETE+     | MAX3945ETE+       | 02-Mar-2015 | 28-Aug-2016 | The part was not released                          |
| Discontinuance | MX7841AS         | N/A               | 02-Mar-2015 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | MX7841BS         | N/A               | 02-Mar-2015 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | MAX7481ETI+      | N/A               | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAX7376CMQT      | N/A               | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAX9125EUE       | N/A               | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAX3953UGK-D     | N/A               | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | VT231TCX-ADJ     | VT231TFCX-ADJ     | 29-Aug-2014 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | VT232TCX-ADJ     | VT232TFCX-ADJ     | 29-Aug-2014 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | VT232TCR-ADJ     | VT232TFCX-ADJ     | 29-Aug-2014 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | VT233TCR-ADJ-001 | VT233TFCX-ADJ-001 | 29-Aug-2014 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | VT233TCX-ADJ     | VT233TFCX-ADJ     | 29-Aug-2014 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | VT233TCX-ADJ-001 | VT233TFCX-ADJ-001 | 29-Aug-2014 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | VT232AWCX-ADJ    | N/A               | 29-Aug-2014 | 28-Aug-2016 | The part was not released                          |
| Discontinuance | VT232WC-ADJ      | VT232WFC-ADJ      | 29-Aug-2014 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | VT232WCX-ADJ     | VT232WFCX-ADJ     | 29-Aug-2014 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | VT233WCX-ADJ     | VT233WFCX-ADJ     | 29-Aug-2014 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | VT245BWFQR-ADJ   | N/A               | 29-Aug-2014 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | VT245BWFQ-ADJ    | N/A               | 29-Aug-2014 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | VT1156SFQX-006   | N/A               | 29-Aug-2014 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | VT245WFQX-ADJ    | N/A               | 29-Aug-2014 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | VT245BWFQX-ADJ   | N/A               | 29-Aug-2014 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | VT245WFQR-ADJ    | N/A               | 29-Aug-2014 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | VT1193SFQ        | N/A               | 29-Aug-2014 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | VT1193SFQX       | N/A               | 29-Aug-2014 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAXQ305J-0000+   | N/A               | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAXQ610A-9411+   | N/A               | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAX7316AEE+      | N/A               | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAXQ8913X-0000+  | N/A               | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |

| Discontinuance | DS3510T+          | N/A             | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
|----------------|-------------------|-----------------|-------------|-------------|--|
| Discontinuance | DS3991Z+HB        | N/A             | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | DS3991Z+PP        | N/A             | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | DS3991Z+PP/V      | N/A             | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | DS3991Z+T&R/PP    | N/A             | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAX17143ETJ+TC61  | N/A             | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAX3785UBL        | MAX3785UBL+     | 02-Mar-2015 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | MAX3785UTT-T      | MAX3785UTT+T    | 02-Mar-2015 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | MAX3800UHJ        | MAX3800UHJ+     | 02-Mar-2015 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | MAX3804ETE        | MAX3804ETE+     | 02-Mar-2015 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | MAX7375AXR375     | MAX7375AXR365+  | 02-Mar-2015 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | ICM7211MIPL       | ICM7211MIPL+    | 02-Mar-2015 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | ICM7218AIJI       | ICM7218AIJI+    | 02-Mar-2015 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | ICM7218DIJI       | ICM7218DIPI+    | 02-Mar-2015 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | MAX3750CEE-TG075  | MAX3750CEE+T    | 02-Mar-2015 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | MAX3983UGK+W      | MAX3983UGK+D    | 29-Aug-2014 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAX3880ECB+D      | N/A             | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAX7316AEE+T      | N/A             | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAX7316ATE+       | N/A             | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAX6957APL        | MAX6957ATL+     | 02-Mar-2015 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | MAX7231BFIQH-TD   | MAX7231BFIQH+TD | 02-Mar-2015 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | VT1311SFCX        | N/A             | 29-Aug-2014 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | DS1315-5          | DS1315-5+       | 29-Aug-2014 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | DS60R-U           | N/A             | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | VT7751SFPQ        | MAX20767EPS+    | 29-Aug-2014 | 28-Aug-2016 | The part was not released                          |
| Discontinuance | DS1620S-001       | N/A             | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAX9530CXV+       | N/A             | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAX9530EVKIT+     | N/A             | 29-Aug-2014 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | VT8024FQD-C00     | N/A             | 29-Aug-2014 | 28-Aug-2016 | The part was not released                          |
| Discontinuance | 806-0598-21-TD    | N/A             | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | LMX339HASD+T      | MAX9094ASD+T    | 31-Aug-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | LMX331AUK+        | MAX9647AUK+T    | 31-Aug-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | VT7410FQR-ADJ     | MAX20732EPL+T   | 29-Aug-2014 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | VT231TCR-ADJ      | VT231TFCX-ADJ   | 29-Aug-2014 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | DS1867SN-050/T&R/ | N/A             | 29-Aug-2014 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAX11643EEG       | N/A             | 29-Aug-2014 | 28-Aug-2016 | The part was not released                          |

| Discontinuance | MAX11632EEG       | N/A            | 29-Aug-2014 | 28-Aug-2016 | The part was not released                          |
|----------------|-------------------|----------------|-------------|-------------|--|
| Discontinuance | MAX11622EEG       | N/A            | 29-Aug-2014 | 28-Aug-2016 | The part was not released                          |
| Discontinuance | MAX5270AEMH       | N/A            | 02-Mar-2015 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | MAX44253EVKIT#    | N/A            | 29-Aug-2014 | 28-Aug-2016 | The part was not released                          |
| Discontinuance | MAX1810ESA+       | MAX8869EUE10+T | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAX6603EVKIT      | MAX6603EVKIT+  | 29-Aug-2014 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | DS3905U-020+T&R   | N/A            | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | LMX331HAUK+       | MAX9647AUK+T   | 31-Aug-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | LMX331HAXK+T      | MAX9648AXK+T   | 31-Aug-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | LMX339AUD+T       | MAX9095AUD+T   | 31-Aug-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | LMX339ASD+T       | MAX9094ASD+T   | 31-Aug-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | LMX331AXK+        | MAX9648AXK+T   | 31-Aug-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | VT7410FQN-ADJ     | MAX20732EPL+   | 29-Aug-2014 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAX9969ADCCQ+D    | N/A            | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | VT232WCR-ADJ      | VT232WFCX-ADJ  | 29-Aug-2014 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | VT350FCX-ADJ-001  | VT350AFCX-ADJ  | 29-Aug-2014 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | VT245WFQ-ADJ      | N/A            | 29-Aug-2014 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | VT1193SFQR        | N/A            | 29-Aug-2014 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAX3953EVKIT      | N/A            | 29-Aug-2014 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAXQ616V-L001+T   | N/A            | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAX3786UTJ        | MAX3786UTJ+    | 02-Mar-2015 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | ICM7211AMIQH-D    | ICM7211AMIQH+D | 02-Mar-2015 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | MAX11624EEG       | N/A            | 29-Aug-2014 | 28-Aug-2016 | The part was not released                          |
| Discontinuance | DS3690T+          | N/A            | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAXQ616V-L000+T   | N/A            | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MX7537TQ/883B     | N/A            | 02-Mar-2015 | 28-Aug-2016 | Part can no longer be manufactured                 |
| Discontinuance | MAX6198BESA-TG069 | MAX6198BESA+T  | 02-Mar-2015 | 28-Aug-2016 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | MAX11640EEG       | N/A            | 29-Aug-2014 | 28-Aug-2016 | The part was not released                          |