

PCN Number:	20180831000	PCN Date:	Sept. 5, 2018
Title:	Datasheet for LM2574, LM2574HV		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.



LM2574, LM2574HV

SNVS104E – JUNE 1999 – REVISED JULY 2018

Changes from Revision D (April 2016) to Revision E

Page

- | | |
|---|---|
| • Added links for WEBENCH | 1 |
| • maximum supply voltage in <i>Abs Max Ratings</i> from "4.5" to "45" to correct typo | 4 |

The datasheet number will be changing.

Device Family	Change From:	Change To:
LM2574, LM2574HV	SNVS104D	SNVS104E

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/LM2574>

Reason for Change:

To accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

LM2574HVM-12/NOPB	LM2574HVMX-12/NOPB	LM2574HVN-5.0/NOPB	LM2574MX-12/NOPB
LM2574HVM-15	LM2574HVMX-15/NOPB	LM2574HVN-ADJ/NOPB	LM2574MX-3.3/NOPB
LM2574HVM-15/NOPB	LM2574HVMX-3.3/NOPB	LM2574M-12/NOPB	LM2574MX-5.0
LM2574HVM-3.3/NOPB	LM2574HVMX-5.0	LM2574M-3.3/NOPB	LM2574MX-5.0/NOPB
LM2574HVM-5.0	LM2574HVMX-5.0/NOPB	LM2574M-5.0	LM2574MX-ADJ/NOPB
LM2574HVM-5.0/NOPB	LM2574HVMX-ADJ/NOPB	LM2574M-5.0/NOPB	LM2574N-12/NOPB
LM2574HVM-ADJ	LM2574HVN-12/NOPB	LM2574M-ADJ	LM2574N-3.3/NOPB
LM2574HVM-ADJ/NOPB	LM2574HVN-15/NOPB	LM2574M-ADJ/NOPB	LM2574N-5.0/NOPB
LM2574N-ADJ/NOPB			

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com

