

PCN Number:	20170614002	PCN Date:	June 15, 2017
Title:	Datasheet for DRV5023-Q1		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.



DRV5023-Q1

SLIS163G – DECEMBER 2014 – REVISED MARCH 2017

Changes from Revision F (September 2016) to Revision G

Page

- Added the output jitter parameter to the *Switching Characteristics* table 6
- Added the *Output Jitter Characteristic* section 15

The datasheet number will be changing.

Device Family	Change From:	Change To:
DRV5023-Q1	SLIS163F	SLIS163G

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/DRV5023-Q1>

Reason for Change:

To accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

DRV5023AJEDBZRQ1	DRV5023AJQDBZTQ1	DRV5023BIELPGMQ1	DRV5023BIQLPGQ1
DRV5023AJEDBZTQ1	DRV5023AJQLPGMQ1	DRV5023BIELPGQ1	DRV5023FAEDBZRQ1
DRV5023AJELPGMQ1	DRV5023AJQLPGQ1	DRV5023BIQDBZRQ1	DRV5023FIEDBZRQ1
DRV5023AJELPGQ1	DRV5023BIEDBZRQ1	DRV5023BIQDBZTQ1	
DRV5023AJQDBZRQ1	DRV5023BIEDBZTQ1	DRV5023BIQLPGMQ1	

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com