



#### PCN# : P6A1AAB Issue Date : Oct. 13, 2016

### **Information Only Notification**

This is to inform you that a change is being made to the following products.

This is a minor change that has no impact on product quality, reliability, electrical or mechanical performance. Affected products will remain fully compliant to all published specifications. Notification is being made for informational purposes only and there is no approval required. Products incorporating this change may be shipped interchangeably with existing unchanged products on or after the issue date of this notification.

Please contact your local Customer Quality Engineer if you have any questions regarding this notification.

#### **Implementation of change:**

Description of Change (From) : For device FTL11639UCX: Carrier tape 3M091551.

For device FUSB300UCX and FUSB300CUCX: Carrier tape 3M063041.

Description of Change (To) : For device FTL11639UCX: Carrier tape 3M118631.

For device FUSB300UCX and FUSB300CUCX: Carrier tape 3M082881.

Except for pocket dimension change, other critical parameter such as tape width, pitch, sprocket pitch, material and supplier remains the same.

	Affected Device	Changes	Carrier Tape	Dimension Ao	Dimension Bo	Dimension Ko	
		FTL11639UCX	Current	3M091551	1.55	1.96	0.75
			New	3M118631	1.44	1.74	0.75
		FUSB300UCX FUSB300CUCX	Current	3M063041	1.45	1.45	0.80
			New	3M082881	1.35	1.35	0.76

Reason for Change:

Tighten fitting tolerance for additional assurance that the unit does not rotate out of position during handling, storage, and transfer.





# Affected Product(s):

FTL11639UCX FUSB300CUCX FUSB300UCX

## Appendix A: Changed Products

C`•{{ ^}:

PCN Number : P6A1AAB

Customer Name :

Product	Customer Part Number	BBB	Drawing
FTL11639UCX		Y	Ν
FUSB300CUCX		Y	Ν