_____

User Registration
Register today to create your account on Silabs.com. Your personalized profile allows you to receive technical document updates, new product announcements, "how-to" and design documents, product change notices (PCN) and other valuable content available only to registered users. http://www.silabs.com/profile

Bulletin Date: 8/19/2015	Bulletin Effective Date: 8/19/2015	
Title: CP2112 Errata		
Originator: Ramya Kota	**Phone:** 512-532-5907	**Dept:** Marketing
Customer Contact: Kathy Haggar	**Phone:** 512-532-5261	**Dept:** Sales
Bulletin Details		
Description: An errata document for CP2112 has been issued and is available at www.silabs.com.		
Reason: If the autoReadRespond feature is used with the HidSmbus_AddressReadRequest() API, HidSmbus_GetReadResponse() may return incorrect data where the first bytes of the response are overwritten by the target address.		
Product Identification: CP2112-F02-GM CP2112-F02-GMR		
This change is considered a minor change which does not affect form, fit, function, quality, or reliability. The information is being provided as a customer courtesy. Please contact your local Silicon Labs sales representative with any questions about this notification. A list of Silicon Labs sales representatives may be found at www.silabs.com		
Customer Actions Needed: Review the errata document and take corrective action if applicable.		

_____

W7206F2 Silicon Labs Bulletin rev M
The information contained in this document is PROPRIETARY to Silicon Laboratories, Inc. and shall not be reproduced or used in part or whole without Silicon Laboratories' written consent. The document is uncontrolled if printed or electronically saved. Pg 3