

CURRENT DATE: 11-MARCH-2014

TE CONNECTIVITY

PRODUCT CHANGE  
NOTIFICATION

---

PRODUCT CHANGE NOTIFICATION NO: E-14-003309  
PCN DATE: 05-MAR-14

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**GENERAL PRODUCT DESCRIPTION:**

AMP MCP 2.8 Product Group Drawing

**DESCRIPTION OF CHANGE:**

drawing mistakes corrected: Dimensions 6.3-0.2 and 4.2-0.2 (spring). Wrong tolerances only on Rev. J8, adapted to older revisions.

**REASON FOR CHANGE:**

Document Clarification. drawing mistake

**ESTIMATE DATE:**

**LAST ORDER DATE:**

(OBSOLETE PARTS ONLY)

**LAST SHIP DATE:**

(OBSOLETE PARTS ONLY)

**FIRST DATE TO SHIP CHANGED PARTS:**

(CHANGED PARTS ONLY)

**LAST DATE FOR MIXED  
SHIPMENTS:**

(CHANGED PARTS ONLY)

CURRENT DATE: 11-MARCH-2014

PRODUCT CHANGE

---

PRODUCT CHANGE NOTIFICATION NO: E-14-003309  
PCN DATE: 05-MAR-14

---

DOCUMENTATION BEING MODIFIED

Customer Drawing  
1355036



CURRENT DATE: 11-MARCH-2014

TE CONNECTIVITY

PRODUCT CHANGE  
NOTIFICATION

---

PRODUCT CHANGE NOTIFICATION NO: E-14-003309

PCN DATE: 05-MAR-14

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

GENERAL PRODUCT DESCRIPTION:

AMP MCP 2.8 Product Group Drawing

DESCRIPTION OF CHANGE:

drawing mistakes corrected: Dimensions 6.3-0.2 and 4.2-0.2 (spring). Wrong tolerances only on Rev. J8, adapted to older revisions.

REASON FOR CHANGE:

Document Clarification. drawing mistake

CURRENT DATE: 11-MARCH-2014

TE CONNECTIVITY

PRODUCT CHANGE  
NOTIFICATION

---

PRODUCT CHANGE NOTIFICATION NO: E-14-003309

PCN DATE: 05-MAR-14

---

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts, and Last Date for Mixed Shipments apply only to parts explicitly on this PCN under 'PARTS BEING MODIFIED' or 'Parts being Discontinued or available with Alternates heading' (if any).

DOCUMENTATION BEING MODIFIED	CUSTOMER SPECIFIC PARTS WITHIN THE DOCUMENT	DOCUMENTATION REVISIONS
Customer Drawing 1355036	1-968849-1	Old Revision: J8

---

---

CURRENTDATE: 11-MARCH-2014

TE CONNECTIVITY

PRODUCT CHANGE  
NOTIFICATION

---

PRODUCT CHANGE NOTIFICATION NO: E-14-003309  
PCN DATE: 05-MAR-14

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

GENERAL PRODUCT DESCRIPTION:

AMP MCP 2.8 Product Group Drawing

DESCRIPTION OF CHANGE:

drawing mistakes corrected: Dimensions 6.3-0.2 and 4.2-0.2 (spring). Wrong tolerances only on Rev. J8, adapted to older revisions.

REASON FOR CHANGE:

Document Clarification. drawing mistake

CURRENTDATE: 11-MARCH-2014

TE CONNECTIVITY

PRODUCT CHANGE  
NOTIFICATION

---

PRODUCT CHANGE NOTIFICATION NO: E-14-003309  
PCN DATE: 05-MAR-14

---

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts, and Last Date for Mixed Shipments apply only to parts explicitly on this PCN under 'PARTS BEING MODIFIED' or 'Parts being Discontinued or available with Alternates heading' (if any).

DOCUMENTATION BEING MODIFIED

CUSTOMER SPECIFIC PARTS  
WITHIN THE DOCUMENT

DOCUMENTATION REVISIONS

Customer Drawing  
1355036

1-968849-2

Old Revision: J8