

June 3, 2011

To: Our Valued Customers

Attention: Procurement Manager

Subject: **PLC11056 – Product EOL/Obsolescence Notification**

You are hereby provided notice that the Intersil products included on the attached parts list are being discontinued. As a valued customer, and one that has previously purchased one or more of such parts, Intersil Corporation is pleased to offer you a final life-of-type procurement for these parts. Recognizing that you will need some time to analyze your requirements, Intersil will accept orders for these products through the LTB/WTHD date provided in the attached list. All shipments under such orders shall be scheduled no later than the SHIP/OBSOLETE date provided. Intersil will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Please review the lists and make adjustments as necessary in your database.

The information contained herein is intended for the recipients use only. Please limit the distribution of this material to those individuals within your immediate organization having a need to act upon the information. In the event that additional distribution outside of your internal organization is necessary, please notify Intersil and the distribution list for discontinued products will be updated as appropriate.

If you are considering a redesign, and require assistance, please contact your local Sales or Rep office, or the Intersil Corporate Line, 1-888-468-3774, for our Central Applications Department.

*Carl Sapp*  
*GCCN Customer Relations Dept.*  
*Intersil Corporation*

<b>Exact Intersil Part # No other variation is being impacted.</b>	<b>Notice PLC11056 Issue Date</b>	<b>LTB / WTHD Date</b>	<b>SHIP/ OBSOLETE Date</b>	<b>Replacement/ Similar/ Re-Design</b>
ACS74DMSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962F9679901VCC	3-Jun-11	30-Dec-11	3-Jun-12	NONE
ACS74HMSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962F9679901V9A	3-Jun-11	30-Dec-11	3-Jun-12	NONE
ACS74KMSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962F9679901VXC	3-Jun-11	30-Dec-11	3-Jun-12	NONE
ACS74KMSRS2732	3-Jun-11	30-Dec-11	3-Jun-12	NONE
CD40106BDMSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962R9660301VCC	3-Jun-11	30-Dec-11	3-Jun-12	NONE
CD40106BHSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962R9660301V9A	3-Jun-11	30-Dec-11	3-Jun-12	NONE
CD40106BKMSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962R9660301VXC	3-Jun-11	30-Dec-11	3-Jun-12	NONE
CD40106BKMSRS2732	3-Jun-11	30-Dec-11	3-Jun-12	NONE
CD40106BKMSRS9000	3-Jun-11	30-Dec-11	3-Jun-12	NONE
CD40106BKMSRS9002	3-Jun-11	30-Dec-11	3-Jun-12	NONE
CD40106BKNSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962R9660302VXC	3-Jun-11	30-Dec-11	3-Jun-12	NONE
HCS132DMSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962R9572601VCC	3-Jun-11	30-Dec-11	3-Jun-12	NONE
HCS132DMSRS9000	3-Jun-11	30-Dec-11	3-Jun-12	NONE
HCS132HMSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962R9572601V9A	3-Jun-11	30-Dec-11	3-Jun-12	NONE
HCS132KMSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962R9572601VXC	3-Jun-11	30-Dec-11	3-Jun-12	NONE
HCS132KMSRS9000	3-Jun-11	30-Dec-11	3-Jun-12	NONE
HCS139DMSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962R9580401VEC	3-Jun-11	30-Dec-11	3-Jun-12	NONE
HCS139KMSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962R9580401VXC	3-Jun-11	30-Dec-11	3-Jun-12	NONE
HCS27DMSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962R9578001VCC	3-Jun-11	30-Dec-11	3-Jun-12	NONE
HCS27HMSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962R9578001V9A	3-Jun-11	30-Dec-11	3-Jun-12	NONE
HCS27KMSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962R9578001VXC	3-Jun-11	30-Dec-11	3-Jun-12	NONE
HCS27KMSRR5310	3-Jun-11	30-Dec-11	3-Jun-12	NONE
HCS27KMSRS2732	3-Jun-11	30-Dec-11	3-Jun-12	NONE
HCTS299DMSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962R9574601VRC	3-Jun-11	30-Dec-11	3-Jun-12	NONE
HCTS299HMSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962R9574601V9A	3-Jun-11	30-Dec-11	3-Jun-12	NONE
HCTS299KMSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962R9574601VXC	3-Jun-11	30-Dec-11	3-Jun-12	NONE

<b>Exact Intersil Part # No other variation is being impacted.</b>	<b>Notice PLC11056 Issue Date</b>	<b>LTB / WTHD Date</b>	<b>SHIP/ OBSOLETE Date</b>	<b>Replacement/ Similar/ Re-Design</b>
HCTS74DMSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962R9576301VCC	3-Jun-11	30-Dec-11	3-Jun-12	NONE
HCTS74HMSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962R9576301V9A	3-Jun-11	30-Dec-11	3-Jun-12	NONE
HCTS74KMSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962R9576301VXC	3-Jun-11	30-Dec-11	3-Jun-12	NONE
HCTS85DMSR	3-Jun-11	30-Dec-11	3-Jun-12	NONE
5962R9576801VEC	3-Jun-11	30-Dec-11	3-Jun-12	NONE
IS9-705RH/PROTO	3-Jun-11	30-Dec-11	3-Jun-12	ISL705ARHF/PROTO
IS9-705RH-8	3-Jun-11	30-Dec-11	3-Jun-12	ISL705ARHQF
5962R0053801QXC	3-Jun-11	30-Dec-11	3-Jun-12	5962R1121301QXC
IS9-705RH-8S2732	3-Jun-11	30-Dec-11	3-Jun-12	ISL705ARHQF
IS9-705RH-8S9000	3-Jun-11	30-Dec-11	3-Jun-12	ISL705ARHQF
IS9-705RH-Q	3-Jun-11	30-Dec-11	3-Jun-12	ISL705ARHVF
5962R0053801VXC	3-Jun-11	30-Dec-11	3-Jun-12	5962R1121301VXC
IS9-705RH-QS2730	3-Jun-11	30-Dec-11	3-Jun-12	ISL705ARHVF
IS9-705RH-QS2732	3-Jun-11	30-Dec-11	3-Jun-12	ISL705ARHVF
IS9-705RH-QS9000	3-Jun-11	30-Dec-11	3-Jun-12	ISL705ARHVF
IS9-705RH-QS9002	3-Jun-11	30-Dec-11	3-Jun-12	ISL705ARHVF
ISL28274FAZ	3-Jun-11	30-Dec-11	3-Jun-12	ISL28272FAZ
ISL28274FAZ-T7	3-Jun-11	30-Dec-11	3-Jun-12	ISL28272FAZ-T7
ISL28278FAZ	3-Jun-11	30-Dec-11	3-Jun-12	ISL28288FBZ
ISL28278FAZ-T7	3-Jun-11	30-Dec-11	3-Jun-12	ISL28288FBZ-T7
ISL28474FAZ	3-Jun-11	30-Dec-11	3-Jun-12	ISL28272FAZ
ISL28474FAZ-T7	3-Jun-11	30-Dec-11	3-Jun-12	ISL28272FAZ-T7
ISL28478FAZ	3-Jun-11	30-Dec-11	3-Jun-12	ISL28488FVZ
ISL28478FAZ-T7	3-Jun-11	30-Dec-11	3-Jun-12	ISL28488FVZ-T7
ISL28488FAZ	3-Jun-11	30-Dec-11	3-Jun-12	ISL28488FVZ
ISL28488FAZ-T7	3-Jun-11	30-Dec-11	3-Jun-12	ISL28488FVZ-T7
ISL58728CRZ	3-Jun-11	3-Jun-11	3-Jun-11	NONE
ISL58728CRZ-T13	3-Jun-11	3-Jun-11	3-Jun-11	NONE
ISL58767CRZ-T13	3-Jun-11	3-Jun-11	3-Jun-11	NONE
ZL1505ALNNT	3-Jun-11	3-Jun-11	3-Jun-11	ZL1505ALNFT
ZL1505ALNNT1	3-Jun-11	3-Jun-11	3-Dec-11	ZL1505ALNFT1
ZL1505ALNNT6	3-Jun-11	3-Jun-11	3-Dec-11	ZL1505ALNFT6
ZL2004ALNN	3-Jun-11	3-Jun-11	3-Jun-11	ZL2004ALNF
ZL2004ALNN-01	3-Jun-11	3-Jun-11	3-Jun-11	ZL2004ALNF-01
ZL2004ALNNT	3-Jun-11	3-Jun-11	3-Jun-11	ZL2004ALNFT
ZL2004ALNNT-01	3-Jun-11	3-Jun-11	3-Jun-11	ZL2004ALNFT-01
ZL2004ALNNT1	3-Jun-11	3-Jun-11	3-Jun-11	ZL2004ALNFT1
ZL2004ALNNT1-01	3-Jun-11	3-Jun-11	3-Jun-11	ZL2004ALNFT1-01
ZL2008ALAF	3-Jun-11	3-Jun-11	3-Jun-11	ZL2008ALBFT
ZL2008ALAF1	3-Jun-11	3-Jun-11	3-Jun-11	ZL2008ALBFT1
ZL2014ALANT-01	3-Jun-11	3-Jun-11	3-Jun-11	ZL2014ALAF1-01
ZL2014ALANT1-01	3-Jun-11	3-Jun-11	3-Jun-11	ZL2014ALAF1-01
ZL2014ALANT6-01	3-Jun-11	3-Jun-11	3-Jun-11	ZL2014ALAF6-01
ZL2014ALANT6-01R5448	3-Jun-11	3-Jun-11	3-Jun-11	NONE

<b>Exact Intersil Part # No other variation is being impacted.</b>	<b>Notice PLC11056 Issue Date</b>	<b>LTB / WTHD Date</b>	<b>SHIP/ OBSOLETE Date</b>	<b>Replacement/ Similar/ Re-Design</b>
ZL2103ALAN	3-Jun-11	3-Jun-11	3-Jun-11	ZL2103ALAF
ZL2103ALANT	3-Jun-11	3-Jun-11	3-Jun-11	ZL2103ALAFK
ZL2103ALANTK	3-Jun-11	3-Jun-11	3-Jun-11	ZL2103ALAFK
ZL2106ALBN	3-Jun-11	3-Jun-11	3-Jun-11	ZL2106ALCF
ZL2106ALBNT	3-Jun-11	3-Jun-11	3-Jun-11	ZL2106ALCFT
ZL2106ALBNTK	3-Jun-11	3-Jun-11	3-Jun-11	ZL2106ALCFTK
ZL2106ALCN	3-Jun-11	3-Jun-11	3-Jun-11	ZL2106ALCF
ZL2106ALCNT	3-Jun-11	3-Jun-11	3-Jun-11	ZL2106ALCFT
ZL2106ALCNTK	3-Jun-11	3-Jun-11	3-Jun-11	ZL2106ALCFTK
ZL2106ALCNTR5451	3-Jun-11	3-Jun-11	3-Jun-11	NONE
ZL8100ALAN	3-Jun-11	3-Jun-11	3-Jun-11	ZL8100ALAF
ZL8100ALANT	3-Jun-11	3-Jun-11	3-Jun-11	ZL8100ALAFK
ZL8100ALANTK	3-Jun-11	3-Jun-11	3-Jun-11	ZL8100ALAFK
ZL8100ALANTKR5457	3-Jun-11	3-Jun-11	3-Jun-11	ZL8100ALAFK5457
ZL8101ALAN	3-Jun-11	3-Jun-11	3-Jun-11	ZL8101ALAF
ZL8101ALANT	3-Jun-11	3-Jun-11	3-Jun-11	ZL8101ALAFK
ZL8101ALANTK	3-Jun-11	3-Jun-11	3-Jun-11	ZL8101ALAFK