


Littelfuse, Inc. 8755 West Higgins Road, Suite 500 Chicago, IL 60631 USA (773) 628-1000

May 10, 2019

Littelfuse PCN 41318_TVS Diode SLD8S Package Carrier Tape Optimization

To: Our Valued Customers,

To optimize carrier tape of TVS Diode of SLD8S Package (SMTO-263), Littelfuse would like to notify you a change of carrier tape.



The optimization does not impact any FIT, Form or Function of the finished product, and will be implemented immediately.

Parts to be impacted by this change, please refer to the attached parts list.

Form, Fit, Function changes: None

Part number changes: None Effective date: Immediately Replacement products: N/A

Last time buy: N/A

This notification is for your acknowledgment. If you have any other questions or concerns, please feel free to contact your local Sales Office.

We value your business and look forward to assisting you whenever possible.

Sincerely and Best Regards,

Victoria You Inside Product Specialist Automotive TVS & Hi-Rel TVS & SIDACtor Semiconductor Business Unit, Wuxi, China Tel: +86 510 85277701 ext. 7710 VYou@Littelfuse.com



Charlie Cai Global Product Manager Automotive TVS and Hi-Rel TVS Semiconductor Business Unit, Wuxi, China Tel: +86 510 85277768

CCai@littelfuse.com

| Part Number |
|-------------|
| SLD8S12A |
| SLD8S13A |
| SLD8S14A |
| SLD8S15A |
| SLD8S16A |
| SLD8S17A |
| SLD8S18A |
| SLD8S20A |
| SLD8S22A |
| SLD8S24A |
| SLD8S26A |
| SLD8S27A |
| SLD8S28A |
| SLD8S30A |
| SLD8S33A |
| SLD8S36A |
| SLD8S40A |
| SLD8S45A |
| SLD8S48A |
| SLD8S51A |
| SLD8S57A |
| |