



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001001

DATE: 01-Sep-2020

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS1225Y-150+	DS1225AD-150+	01-Sep-2020	28-Feb-2021	Part can no longer be manufactured
Discontinuance	DS1225Y-150IND+	DS1225AD-150IND+	01-Sep-2020	28-Feb-2021	Part can no longer be manufactured
Discontinuance	DS1225Y-200+	DS1225AD-200+	01-Sep-2020	28-Feb-2021	Part can no longer be manufactured
Discontinuance	DS1858E-050+	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	DS1862AB+	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	DS1862AB+T&R	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	DS1862B+	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	DS1862B+T&R	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	DS1873T+	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	DS1874T+	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	DS1874T+T&R	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	DS1875RT+	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	DS1875RT+T&R	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	DS1875T+	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	DS1875T+T&R	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	DS4301U-200+	N/A	03-Mar-2021	30-Aug-2021	Part can no longer be manufactured
Discontinuance	IC0400C778BF+LTB	N/A	01-Sep-2020	28-Feb-2021	Part can no longer be manufactured
Discontinuance	MAX1279BETC+	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	MAX14737EWL+	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	MAX14737EWL+T	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	MAX3268CUB+	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	MAX3634ETM+	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	MAX3669EHJ+	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	MAX3669EHJ+T	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	MAX3711ETG+	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	MAX3711ETG+T	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 02-Oct-2020

Discontinuance	MAX3747AEUB+TC99	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	MAX3761EEP+	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	MAX3761EEP+T	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	MAX3762EEP+	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	MAX3762EEP+T	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	MAX3766EEP+	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	MAX3766EEP+T	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	MAX9725BEBC+G45	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	MAX9725BEBC+TG45	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured
Discontinuance	MAX9725CEBC+TG45	N/A	01-Sep-2021	28-Feb-2022	Part can no longer be manufactured