



Not Recommended for New Design: Various AQV258xxx PhotoMOS Relays

NRFND.PG0001. 12.26.2018

12.26.2018

| | |
|--|--|
| About This Notice: | Panasonic has changed the status of part numbers AQV258HA, AQV258HAX and AQV258HAZ to Not Recommended For New Design due to plans for discontinuation in the future. |
| Features: | |
| Effective Date: | Immediate |
| Affected Parts and/or Replacements: | See attached. |
| Datasheet(s): | No datasheet available as these are custom part numbers. |
| Notes: | Custom part may be available after spec review activity. |