

From time to time we find it necessary to change, modify, or replace our product offering. These changes are usually the result of advancements in technology that offer improvements in performance or manufacturability. In this case the immediate unavailability of critical component parts, (generally of an earlier technology) has caused the obsolescence of the outdated product family.

We sincerely appreciate your business and will make every effort to work with you during your transition to new power supplies. In some cases of obsolescence, a new advanced model has been introduced to replace the existing power supplies.

If you have any questions or need specific application assistance, please contact us (you may visit https://www.artesyn.com/contact. Email to productsupport.ep@Artesyn.com or call 1- 888-412-7832) or your local sales representative to assist you. Thank you for your continued patronage.

The following models have been marked as EOL:

Model No	Replacement Model	Replacement Info	LTB start	LTB end
SIL30C- 12SADJ-HJ		No form/fit/function alternative available	07/23/2019	07/26/2019
SIL30C- 12SADJ-VJ		No form/fit/function alternative available	07/23/2019	07/26/2019