

## Product Change Notice

**Issue Date: 30 Jan 2019****Change Type:**

Device marking or labelling method

**Parts Affected:**

HCPL-181	HCPL-354
----------	----------

All associated options will also be affected. See Appendix for full part number list.

**Description and Extent of Change:**

Additional "A" marking before the part number marking.

**Reasons for Change:**

Process standardization for better marking quality.

**Effect of Change on Fit, Form, Function, Quality, or Reliability:**

There is no change to the electrical characteristics of the product.

**Effective Date of Change:**

Products shipments using this change will begin with datecode starting from 1919.

**Qualification Data:**

Not applicable. This change had no impact to product reliability.

---

These changes have been reviewed and approved by Broadcom Limited engineers and managers per Broadcom Limited procedure: Change Control and Customer Notification, 5962-6052-80.

Please contact your Broadcom Limited field sales for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.

**Appendix:**

<b>Affected Part Number</b>
HCPL-181-000E
HCPL-181-00AE
HCPL-181-00BE
HCPL-181-00CE

HCPL-181-00DE
HCPL-181-060E
HCPL-181-06AE
HCPL-181-06BE
HCPL-181-06CE
HCPL-181-06DE
HCPL-354-000E
HCPL-354-00AE
HCPL-354-060E
HCPL-354-06AE