

Product Change Notification (PCN)

PCN Number

505566

Date Issued

August 14, 2018

Reason for Change

Packaging Method/Quantity Changing

Change Type Description

This letter is to inform you that the part(s) referenced in this notice will undergo packaging specification changes that may include new container sizes, quantities or changes to the label. No changes will be made to the product as a result of this change.

Reason for Short Notice

Corrective Actions

Assessment of Change

No change to parts/components FFF

Internal Molex Qualification Date

June 23, 2018

Sample Availability Date (Changed Part)

June 23, 2018

Planned Implementation Date

August 30, 2018

Before Change

NO	Type	Before						After					
		Now							New(Propose)				
		PN -				F DG MOQ	Global DU -	PN -		New Minimum Package Quanti -	DG SPQ ·	DS MOQ	- Global Di
		860252870	Assemb)		100				Assembly	400	400	1200	400
	MLQ of SAP data is		Assembl		100						400	1200	400
1	not times of DU(SPQ)	1061700140	Assembl	400	100	0 100	1000	1061700140	Asseroly	400	400	1200	400
				Now					New(Propose)				
2	DU of SAP data is small than actual DU	PN - 1060120400 1060120200 1060130000	Assembly Assembly	Current Minimum Package Quantity 400 400 400	- DG SPQ - 100	100	100	PN 1060120400 1060120200 1060103000	Assemble Assemble		0G SPQ - 400 400 400	DS MOQ 400 400 400	Global Di 400 400 400
	MLQ of SAP data is 1				Now						New(Pro	annel .	
3	pcs that very old data when they are in sample process		Type - Assenbly Assenbly	Current Minimum Package Quantity 190 800 200	06 SPQ #	0 1	Global DU =	9% - 1061236700 861271100 1061810008	Assembly Assembly	New Minimum Package Quanti - 160 800 200	DG SPQ - 160 800 200	DG MOQ - 160 800 200	6fobal DU - 160 800 200
	SAP data have update			New				\equiv	New(Propose)				
4	in interial ECN ,now we just notice customer.Because most of product which use by ourself for assembly process	PN - 860105010 860107010 860190010	Moiding	Current Minimum Package Quantity - 2000 2000 2000	DG SPQ - 1 2000 2000 2000	96 MOQ - 2000 2000 2000 2000	Global DU - 2000 2000 2000 2000	860105010 860107010 860190010	Molding Molding	New Minimure Package Quarti + 2000 2000 2000	06 SPQ - 2000 2000 2000 2000	06 MOQ - 2000 2000 2000 2000	Global Du - 2000 2000 2000 2000

Above list can not include all attached file for every parts

After Change

Overview

- Reason for change is revise system information

 1> MLQ of SAP data is not the times of actual DU(SPQ),so this cause
- customer place the order with non-SPQ ,we need separate the box , So we just correct the SAP to meet actual SPQ.
- 2> SAP data is 1pcs which the product in old sample process, so we need correct it
- 3> For Molding part which most of use by internal use in assembly process,so we have change the SAP base on internal ECN ,now we just let customer know it.
- Product Impact
 - Keep existing design , no impact to fit, form or function.
- Part Number Impact
 - Please refer to the attached



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "PCN Notification:505566" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com

				Now		New(Propose)					
		Package				Package Q'ty					
PN	Type	Q'ty	DG SPQ	DG MOQ	Global DU	After change	DG SPQ	DG MOQ	Global DU		
1065121008	Molding	6000	6000	6000	6000	6000	6000	6000	6000		

Package Q'ty	DG SPQ	DG MOQ	Global DU	Remark
0	0	0	0	Need PCN

Molex Part #
