

PCN Number:	20170713000	PCN Date:	July 26, 2017
Title:	Datasheet for BQ21040		
Customer Contact:	PCN Manager	Dept:	Quality Services
Proposed 1st Ship Date:	October 26, 2017		
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below.



bq21040

SLUSCE2B –APRIL 2016–REVISED MAY 2017

Changes from Revision A (April 2016) to Revision B

Page

- | | |
|--|-------------------|
| <ul style="list-style-type: none"> • Changed MIN and MAX values in the <i>Electrical Characteristics</i> table, Changed MIN and MAX values for Fast charge current factor, KISSET 1 • Added <i>Receiving Notification of Documentation Updates</i> section 1 | <p>1</p> <p>1</p> |
|--|-------------------|

The datasheet number will be changing.

Device Family	Change From:	Change To:
BQ21040	SLUSCE2A	SLUSCE2B

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/BQ21040>

Reason for Change:

To more accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

Electrical specification performance changes as indicated above.

Changes to product identification resulting from this PCN:

None.

Product Affected:

BQ21040DBVR	BQ21040DBVT		
-------------	-------------	--	--

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com

