



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #: U-09-01 Last Buy Deadline for Submission of Order: 13-May-2010

Issue Date: 13-May-2009 Last Eligible Ship Date: 13-Aug-2010

Contact: Russell Willner
 Title: Marketing Manager - Micro Clock Products
 Phone #: 408-284-6564
 Fax #: 408-284-2774
 E-mail: Russell.Willner@idt.com

PRODUCT(S) AFFECTED: ATTACHMENT Yes No

(List Replacement Part #(s), if any)

Selected Standard Packages of Micro Clock devices will be discontinued and replaced by RoHS versions.
 See attachment I for affected part numbers and replacement part numbers.

REASON FOR DISCONTINUANCE:

- Replace slower speed with faster speed offerings Other: _____
- Obsolete Fab Technology / Process _____
- Obsolete Assembly Technology / Process Converting to RoHS versions
- Obsolete Package / Material _____
- Declined Market _____

CUSTOMER NOTIFICATION:

As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before converting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information.

Last time buy orders may be submitted any time prior to the date indicated above. All orders shall be subject to acceptance by IDT at its sole discretion unless otherwise agreed by IDT in writing.

If you have any questions, please feel free to contact your local IDT distributor or sales representative.

Customer: _____ E-Mail Address: _____

Name/Date: _____ Phone#: _____

Title: _____ Fax# : _____

CUSTOMER COMMENTS: _____

IDT ACKNOWLEDGEMENT:

Received By: _____ Date: _____



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: U-09-01

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
1493AGI-19	1493AGI-19LF	181MI-01T	181MI-01LFT
1493AGI-19T	1493AGI-19LFT	181MI-02	181MI-02LF
1493GI-19	1493GI-19LF	181MI-02T	181MI-02LFT
1493GI-19T	1493GI-19LFT	1882AF	1882AFLF
1522M	1522MLF	1882AFT	1882AFLFT
1522MT	1522MLFT	1883AF	1883AFLF
1523M	1523MLF	1883AFT	1883AFLFT
1523MT	1523MLFT	1892Y	1892YLF
1524AM	1524AMLF	1892Y-10	1892Y-10LF
1524AMT	1524AMLFT	1892Y-10T	1892Y-10LFT
1526G	1526GLF	1892Y-14	1892Y-14LF
1526GT	1526GLFT	1892Y-14T	1892Y-14LFT
1527G-110	1527G-110LF	1892YT	1892YLFT
1527G-110T	1527G-110LFT	1893AF	1893AFLF
1562BM-201	1562BM-201LF	1893AFI	1893AFILF
1562BM-201-4	1562BM-201-4LF	1893AFIT	1893AFILFT
1562BM-201T	1562BM-201LFT	1893AFT	1893AFLFT
1574BM	1574BMLF	1893AG	1893AGLF
1574BMT	1574BMLFT	1893AGT	1893AGLFT
180M-01	180M-01LF	1893BF	1893BFLF
180M-01T	180M-01LFT	1893BFI	1893BFILF
180M-03	180M-03LF	1893BFIT	1893BFILFT
180M-03T	180M-03LFT	1893BFT	1893BFLFT
180M-51	180M-51LF	1893BY-10	1893BY-10LF
180M-51T	180M-51LFT	1893BY-10T	1893BY-10LFT
180M-52	180M-52LF	1893BYI-10	1893BYI-10LF
180M-52T	180M-52LFT	1893BYI-10T	1893BYI-10LFT
180M-53	180M-53LF	1893CF	1893CFLF
180M-53T	180M-53LFT	1893CFI	1893CFILF
180MI-01	180MI-01LF	1893CFIT	1893CFILFT
180MI-01T	180MI-01LFT	1893CFT	1893CFLFT
181M-01	181M-01LF	1893Y-10	1893Y-10LF
181M-01T	181M-01LFT	1893Y-10T	1893Y-10LFT
181M-02	181M-02LF	1893YI-10	1893YI-10LF
181M-02T	181M-02LFT	1893YI-10T	1893YI-10LFT
181M-03	181M-03LF	2008BV	2008BVLF
181M-03T	181M-03LFT	2008BVT	2008BVLFT
181M-51	181M-51LF	2008BY-10	2008BY-10LF
181M-51T	181M-51LFT	2008BY-10T	2008BY-10LFT
181M-52	181M-52LF	2059GI-02	2059GI-02LF
181M-52T	181M-52LFT	2059GI-02T	2059GI-02LFT
181M-53	181M-53LF	2304NZG-1	2304NZG-1LF
181M-53T	181M-53LFT	2304NZG-1T	2304NZG-1LFT
181MI-01	181MI-01LF	2304NZGI-1	2304NZGI-1LF



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: U-09-01

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
2304NZGI-1T	2304NZGI-1LFT	2308-2DC8	2308-2DCG8
2305-1DC	2305-1DCG	2308-2DCI	2308-2DCGI
2305-1DC8	2305-1DCG8	2308-2DCI8	2308-2DCGI8
2305-1DCI	2305-1DCGI	2308-2HDC	2308-2HDCG
2305-1DCI8	2305-1DCGI8	2308-2HDC8	2308-2HDCG8
2305-1HDC	2305-1HDCG	2308-2HDCI	2308-2HDCGI
2305-1HDC8	2305-1HDCG8	2308-2HDCI8	2308-2HDCGI8
2305-1HDCI	2305-1HDCGI	2308-3DC	2308-3DCG
2305-1HDCI8	2305-1HDCGI8	2308-3DC8	2308-3DCG8
2305A-1DC	2305A-1DCG	2308-3DCI	2308-3DCGI
2305A-1DC8	2305A-1DCG8	2308-3DCI8	2308-3DCGI8
2305A-1DCI	2305A-1DCGI	2308-4DC	2308-4DCG
2305A-1DCI8	2305A-1DCGI8	2308-4DC8	2308-4DCG8
2305A-1HDC	2305A-1HDCG	2308-4DCI	2308-4DCGI
2305A-1HDC8	2305A-1HDCG8	2308-4DCI8	2308-4DCGI8
2305A-1HDCI	2305A-1HDCGI	2308-5HDC	2308-5HDCG
2305A-1HDCI8	2305A-1HDCGI8	2308-5HDC8	2308-5HDCG8
2305B-1DC	2305B-1DCG	2308-5HDCI	2308-5HDCGI
2305B-1DC8	2305B-1DCG8	2308-5HDCI8	2308-5HDCGI8
2305B-1DCI	2305B-1DCGI	2308-5HPG	2308-5HPGG
2305B-1DCI8	2305B-1DCGI8	2308-5HPG8	2308-5HPGG8
2305B-1HDC	2305B-1HDCG	2308-5HPGI	2308-5HPGGI
2305B-1HDC8	2305B-1HDCG8	2308-5HPGI8	2308-5HPGGI8
2305B-1HDCI	2305B-1HDCGI	2308A-1DC	2308A-1DCG
2305B-1HDCI8	2305B-1HDCGI8	2308A-1DC8	2308A-1DCG8
2305M-1	2305M-1LF	2308A-1DCI	2308A-1DCGI
2305M-1H	2305M-1HLF	2308A-1DCI8	2308A-1DCGI8
2305M-1HT	2305M-1HLFT	2308A-1HDCI	2308A-1HDCGI
2305M-1T	2305M-1LFT	2308A-1HDCI8	2308A-1HDCGI8
2305MI-1H	2305MI-1HLF	2308A-1HPG	2308A-1HPGG
2305MI-1HT	2305MI-1HLFT	2308A-1HPG8	2308A-1HPGG8
2308-1DC	2308-1DCG	2308A-1HPGI	2308A-1HPGGI
2308-1DC8	2308-1DCG8	2308A-1HPGI8	2308A-1HPGGI8
2308-1DCI	2308-1DCGI	2308A-2DC	2308A-2DCG
2308-1DCI8	2308-1DCGI8	2308A-2DC8	2308A-2DCG8
2308-1HDC	2308-1HDCG	2308A-2DCI	2308A-2DCGI
2308-1HDC8	2308-1HDCG8	2308A-2DCI8	2308A-2DCGI8
2308-1HDCI	2308-1HDCGI	2308A-2HDC	2308A-2HDCG
2308-1HDCI8	2308-1HDCGI8	2308A-2HDC8	2308A-2HDCG8
2308-1HPG	2308-1HPGG	2308A-3DC	2308A-3DCG
2308-1HPG8	2308-1HPGG8	2308A-3DC8	2308A-3DCG8
2308-1HPGI	2308-1HPGGI	2308A-3DCI	2308A-3DCGI
2308-1HPGI8	2308-1HPGGI8	2308A-3DCI8	2308A-3DCGI8
2308-2DC	2308-2DCG	2308A-4DC	2308A-4DCG



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: U-09-01

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
2308A-4DC8	2308A-4DCG8	2309A-1HPGI8	2309A-1HPGGI8
2308A-4DCI	2308A-4DCGI	2309B-1DC	2309B-1DCG
2308A-4DCI8	2308A-4DCGI8	2309B-1DC8	2309B-1DCG8
2308B-1DC	2308B-1DCG	2309B-1HDC	2309B-1HDCG
2308B-1DC8	2308B-1DCG8	2309B-1HDC8	2309B-1HDCG8
2308B-1DCI	2308B-1DCGI	2309B-1HDCI	2309B-1HDCGI
2308B-1DCI8	2308B-1DCGI8	2309B-1HDCI8	2309B-1HDCGI8
2308B-1HDC	2308B-1HDCG	2309B-1HPG	2309B-1HPGG
2308B-1HDC8	2308B-1HDCG8	2309B-1HPG8	2309B-1HPGG8
2308B-1HDCI	2308B-1HDCGI	2309B-1HPGI	2309B-1HPGGI
2308B-1HDCI8	2308B-1HDCGI8	2309B-1HPGI8	2309B-1HPGGI8
2308B-1HPG	2308B-1HPGG	2309NZ-1HDC	2309NZ-1HDCG
2308B-1HPG8	2308B-1HPGG8	2309NZ-1HDC8	2309NZ-1HDCG8
2308B-1HPGI	2308B-1HPGGI	2309NZ-1HDCI	2309NZ-1HDCGI
2308B-1HPGI8	2308B-1HPGGI8	2309NZ-1HDCI8	2309NZ-1HDCGI8
2308B-2DC	2308B-2DCG	2309NZ-1HPG	2309NZ-1HPGG
2308B-2DC8	2308B-2DCG8	2309NZ-1HPG8	2309NZ-1HPGG8
2308B-2DCI	2308B-2DCGI	2309NZ-1HPGI	2309NZ-1HPGGI
2308B-2DCI8	2308B-2DCGI8	2309NZ-1HPGI8	2309NZ-1HPGGI8
2308B-3DC	2308B-3DCG	23S05-1DC	23S05-1DCG
2308B-3DC8	2308B-3DCG8	23S05-1DC8	23S05-1DCG8
2308B-4DC	2308B-4DCG	23S05-1DCI	23S05-1DCGI
2308B-4DC8	2308B-4DCG8	23S05-1DCI8	23S05-1DCGI8
2309-1DC	2309-1DCG	23S05-1HDC	23S05-1HDCG
2309-1DC8	2309-1DCG8	23S05-1HDC8	23S05-1HDCG8
2309-1DCI	2309-1DCGI	23S05-1HDCI	23S05-1HDCGI
2309-1DCI8	2309-1DCGI8	23S05-1HDCI8	23S05-1HDCGI8
2309-1HDC	2309-1HDCG	23S05E-1DC	23S05E-1DCG
2309-1HDC8	2309-1HDCG8	23S05E-1DC8	23S05E-1DCG8
2309-1HDCI	2309-1HDCGI	23S05E-1DCI	23S05E-1DCGI
2309-1HDCI8	2309-1HDCGI8	23S05E-1DCI8	23S05E-1DCGI8
2309-1HPG	2309-1HPGG	23S05E-1HDC	23S05E-1HDCG
2309-1HPG8	2309-1HPGG8	23S05E-1HDC8	23S05E-1HDCG8
2309-1HPGI	2309-1HPGGI	23S05E-1HDCI	23S05E-1HDCGI
2309-1HPGI8	2309-1HPGGI8	23S05E-1HDCI8	23S05E-1HDCGI8
2309A-1DC	2309A-1DCG	23S05T-1DC	23S05T-1DCG
2309A-1DC8	2309A-1DCG8	23S05T-1DC8	23S05T-1DCG8
2309A-1DCI	2309A-1DCGI	23S05T-1DCI	23S05T-1DCGI
2309A-1DCI8	2309A-1DCGI8	23S05T-1DCI8	23S05T-1DCGI8
2309A-1HDC	2309A-1HDCG	23S08-1DC	23S08-1DCG
2309A-1HDC8	2309A-1HDCG8	23S08-1DC8	23S08-1DCG8
2309A-1HPG	2309A-1HPGG	23S08-1DCI	23S08-1DCGI
2309A-1HPG8	2309A-1HPGG8	23S08-1DCI8	23S08-1DCGI8
2309A-1HPGI	2309A-1HPGGI	23S08-1HDC	23S08-1HDCG



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: U-09-01

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
23S08-1HDC8	23S08-1HDCG8	23S09E-1DC8	23S09E-1DCG8
23S08-1HDCI	23S08-1HDCGI	23S09E-1DCI	23S09E-1DCGI
23S08-1HDCI8	23S08-1HDCGI8	23S09E-1DCI8	23S09E-1DCGI8
23S08-2DC	23S08-2DCG	23S09E-1HDCI	23S09E-1HDCGI
23S08-2DC8	23S08-2DCG8	23S09E-1HDCI8	23S09E-1HDCGI8
23S08-2DCI	23S08-2DCGI	23S09E-1HPG	23S09E-1HPGG
23S08-2DCI8	23S08-2DCGI8	23S09E-1HPG8	23S09E-1HPGG8
23S08-2HDC	23S08-2HDCG	23S09E-1HPGI	23S09E-1HPGGI
23S08-2HDC8	23S08-2HDCG8	23S09E-1HPGI8	23S09E-1HPGGI8
23S08-3DC	23S08-3DCG	23S09T-1DC	23S09T-1DCG
23S08-3DC8	23S08-3DCG8	23S09T-1DC8	23S09T-1DCG8
23S08-4DCI	23S08-4DCGI	2402M	2402MLF
23S08-4DCI8	23S08-4DCGI8	2402MT	2402MLFT
23S08-5HDC	23S08-5HDCG	252PM	252PMLF
23S08-5HDC8	23S08-5HDCG8	252PMT	252PMLFT
23S08E-1DC	23S08E-1DCG	270PG	270PGLF
23S08E-1DC8	23S08E-1DCG8	270PGI	270PGILF
23S08E-1DCI	23S08E-1DCGI	270PGIT	270PGILFT
23S08E-1DCI8	23S08E-1DCGI8	270PGT	270PGLFT
23S08E-1HDC	23S08E-1HDCG	271PG	271PGLF
23S08E-1HDC8	23S08E-1HDCG8	271PGI	271PGILF
23S08E-1HDCI	23S08E-1HDCGI	271PGIT	271PGILFT
23S08E-1HDCI8	23S08E-1HDCGI8	271PGT	271PGLFT
23S08E-1HPG	23S08E-1HPGG	275G-01	275G-01LF
23S08E-1HPG8	23S08E-1HPGG8	275G-01T	275G-01LFT
23S08E-2DC	23S08E-2DCG	275GI-01	275GI-01LF
23S08E-2DC8	23S08E-2DCG8	275GI-01T	275GI-01LFT
23S08E-2DCI	23S08E-2DCGI	275PG	275PGLF
23S08E-2DCI8	23S08E-2DCGI8	275PGI	275PGILF
23S08E-3DC	23S08E-3DCG	275PGIT	275PGILFT
23S08E-3DC8	23S08E-3DCG8	275PGT	275PGLFT
23S08E-3DCI	23S08E-3DCGI	276PG	276PGLF
23S08E-3DCI8	23S08E-3DCGI8	276PGI	276PGILF
23S08E-4DC	23S08E-4DCG	276PGIT	276PGILFT
23S08E-4DC8	23S08E-4DCG8	276PGT	276PGLFT
23S08E-5HDC	23S08E-5HDCG	280G-02	280G-02LF
23S08E-5HDC8	23S08E-5HDCG8	280G-02T	280G-02LFT
23S09-1DC	23S09-1DCG	280G-13	280G-13LF
23S09-1DC8	23S09-1DCG8	280G-13T	280G-13LFT
23S09-1HDC	23S09-1HDCG	280GI-13	280GI-13LF
23S09-1HDC8	23S09-1HDCG8	280GI-13T	280GI-13LFT
23S09-1HPG	23S09-1HPGG	280PG	280PGLF
23S09-1HPG8	23S09-1HPGG8	280PGI	280PGILF
23S09E-1DC	23S09E-1DCG	280PGIT	280PGILFT



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: U-09-01

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
280PGT	280PGLFT	332M-55T	332M-55LFT
281PG	281PGLF	332M-63	332M-63LF
281PGI	281PGILF	332M-63T	332M-63LFT
281PGIT	281PGILFT	332M-69	332M-69LF
281PGT	281PGLFT	332M-69T	332M-69LFT
290PG	290PGLF	333M-13	333M-13LF
290PGI	290PGILF	333M-13T	333M-13LFT
290PGIT	290PGILFT	341M	341MLF
290PGT	290PGLFT	341M-09	341M-09LF
291G-07	291G-07LF	341M-09T	341M-09LFT
291G-07T	291G-07LFT	341M-14	341M-14LF
291PG	291PGLF	341M-14T	341M-14LFT
291PGI	291PGILF	341MI-20	341MI-20LF
291PGIT	291PGILFT	341MI-20T	341MI-20LFT
291PGT	291PGLFT	341MIP	341MIPLF
301M-28	301M-28LF	341MIPT	341MIPLFT
301M-28T	301M-28LFT	341MP	341MPLF
307G-03	307G-03LF	341MPT	341MPLFT
307G-03T	307G-03LFT	341MT	341MLFT
307M-02	307M-02LF	342M	342MLF
307M-02I	307M-02ILF	342M-02	342M-02LF
307M-02IT	307M-02ILFT	342M-02T	342M-02LFT
307M-02T	307M-02LFT	342M-07	342M-07LF
308R	308RLF	342M-07T	342M-07LFT
308RI	308RILF	342M-14	342M-14LF
308RIT	308RILFT	342M-14T	342M-14LFT
308RT	308RLFT	342M-28	342M-28LF
309R	309RLF	342M-28T	342M-28LFT
309RI	309RILF	342MI-28	342MI-28LF
309RIT	309RILFT	342MI-28T	342MI-28LFT
309RT	309RLFT	342MIP	342MIPLF
331M-26	331M-26LF	342MIPT	342MIPLFT
331M-26T	331M-26LFT	342MP	342MPLF
332M-15	332M-15LF	342MPT	342MPLFT
332M-15T	332M-15LFT	342MT	342MLFT
332M-29	332M-29LF	343M	343MLF
332M-29T	332M-29LFT	343M-09	343M-09LF
332M-33	332M-33LF	343M-09T	343M-09LFT
332M-33T	332M-33LFT	343M-14	343M-14LF
332M-49	332M-49LF	343M-14T	343M-14LFT
332M-49T	332M-49LFT	343M-24	343M-24LF
332M-54	332M-54LF	343M-24T	343M-24LFT
332M-54T	332M-54LFT	343MIP	343MIPLF
332M-55	332M-55LF	343MIPT	343MIPLFT



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: U-09-01

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
343MP	343MPLF	412M-02T	412M-02LFT
343MPT	343MPLFT	414G-01	414G-01LF
343MT	343MLFT	414G-01T	414G-01LFT
345R	345RLF	414G-02	414G-02LF
345R-08	345R-08LF	414G-02T	414G-02LFT
345R-08T	345R-08LFT	422G-07	422G-07LF
345R-27	345R-27LF	422G-07T	422G-07LFT
345R-27T	345R-27LFT	422M-03	422M-03LF
345RI-13	345RI-13LF	422M-03T	422M-03LFT
345RI-13T	345RI-13LFT	422M-15	422M-15LF
345RI-21	345RI-21LF	422M-15T	422M-15LFT
345RI-21T	345RI-21LFT	4231M-03	4231M-03LF
345RIP	345RIPLF	4231M-03T	4231M-03LFT
345RIPT	345RIPLFT	431M-19	431M-19LF
345RP	345RPLF	431M-19T	431M-19LFT
345RPT	345RPLFT	431M-31	431M-31LF
345RT	345RLFT	431M-31T	431M-31LFT
348R	348RLF	432M-70	432M-70LF
348R-02	348R-02LF	432M-70T	432M-70LFT
348R-02T	348R-02LFT	433M-47	433M-47LF
348R-10	348R-10LN	433M-47T	433M-47LFT
348R-10T	348R-10LNT	433M-65	433M-65LF
348R-19	348R-19LF	433M-65T	433M-65LFT
348R-19T	348R-19LFT	445R-02	445R-02LF
348R-20	348R-20LF	445R-02T	445R-02LFT
348R-20T	348R-20LFT	445R-31	445R-31LF
348R-29	348R-29LF	445R-31T	445R-31LFT
348R-29T	348R-29LFT	445R-34	445R-34LF
348RIP	348RIPLF	445R-34T	445R-34LFT
348RIPT	348RIPLFT	448R-01	448R-01LF
348RP	348RPLF	448R-01T	448R-01LFT
348RPT	348RPLFT	454G-22	454G-22LF
348RT	348RLFT	454G-22T	454G-22LFT
355R-23	355R-23LF	455R-19I	455R-19ILF
355R-23T	355R-23LFT	455R-19IT	455R-19ILFT
400M-86	400M-86LF	455R-25	455R-25LF
400M-86T	400M-86LFT	455R-25T	455R-25LFT
409M	409MLF	455R-31	455R-31LF
409MT	409MLFT	455R-31T	455R-31LFT
411M	411MLF	455R-32	455R-32LF
411MT	411MLFT	455R-32T	455R-32LFT
412M-01	412M-01LF	477R-05	477R-05LF
412M-01T	412M-01LFT	477R-05T	477R-05LFT
412M-02	412M-02LF	480G-11	480G-11LF



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: U-09-01

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
480G-11T	480G-11LFT	49FCT3805DQI8	49FCT3805DQG8
480GI-11	480GI-11LF	49FCT3805EPYI	49FCT3805EPYGI
480GI-11T	480GI-11LFT	49FCT3805EPYI8	49FCT3805EPYGI8
487G-25	487G-25LF	49FCT3805EQI	49FCT3805EQGI
487G-25T	487G-25LFT	49FCT3805EQI8	49FCT3805EQGI8
487G-33	487G-33LF	49FCT3805PY	49FCT3805PYG
487G-33T	487G-33LFT	49FCT3805PY8	49FCT3805PYG8
487G-35	487G-35LF	49FCT3805PYI	49FCT3805PYGI
487G-35T	487G-35LFT	49FCT3805PYI8	49FCT3805PYGI8
488R-12	488R-12LF	49FCT3805Q	49FCT3805QG
488R-12T	488R-12LFT	49FCT3805Q8	49FCT3805QG8
488R-39	488R-39LF	49FCT3805QI	49FCT3805QGI
488R-39T	488R-39LFT	49FCT3805QI8	49FCT3805QGI8
49FCT20805PYI	49FCT20805PYGI	49FCT3805SO	49FCT3805SOG
49FCT20805PYI8	49FCT20805PYGI8	49FCT3805SO8	49FCT3805SOG8
49FCT20805QI	49FCT20805QGI	49FCT3805SOI	49FCT3805SOGI
49FCT20805QI8	49FCT20805QGI8	49FCT3805SOI8	49FCT3805SOGI8
49FCT3805APY	49FCT3805APYG	49FCT805APY	49FCT805APYG
49FCT3805APY8	49FCT3805APYG8	49FCT805APY8	49FCT805APYG8
49FCT3805APYI	49FCT3805APYGI	49FCT805APYI	49FCT805APYGI
49FCT3805APYI8	49FCT3805APYGI8	49FCT805APYI8	49FCT805APYGI8
49FCT3805AQ	49FCT3805AQG	49FCT805ASO	49FCT805ASOG
49FCT3805AQ8	49FCT3805AQG8	49FCT805ASO8	49FCT805ASOG8
49FCT3805AQI	49FCT3805AQGI	49FCT805ASOI	49FCT805ASOGI
49FCT3805AQI8	49FCT3805AQGI8	49FCT805ASOI8	49FCT805ASOGI8
49FCT3805ASO	49FCT3805ASOG	49FCT805BTPY	49FCT805BTPYG
49FCT3805ASO8	49FCT3805ASOG8	49FCT805BTPY8	49FCT805BTPYG8
49FCT3805ASOI	49FCT3805ASOGI	49FCT805BTQ	49FCT805BTQG
49FCT3805ASOI8	49FCT3805ASOGI8	49FCT805BTQ8	49FCT805BTQG8
49FCT3805BPY	49FCT3805BPYG	49FCT805BTSO	49FCT805BTSOG
49FCT3805BPY8	49FCT3805BPYG8	49FCT805BTSO8	49FCT805BTSOG8
49FCT3805BPYI	49FCT3805BPYGI	49FCT805CTPY	49FCT805CTPYG
49FCT3805BPYI8	49FCT3805BPYGI8	49FCT805CTPY8	49FCT805CTPYG8
49FCT3805BQ	49FCT3805BQG	49FCT805CTQ	49FCT805CTQG
49FCT3805BQ8	49FCT3805BQG8	49FCT805CTQ8	49FCT805CTQG8
49FCT3805BQI	49FCT3805BQGI	49FCT805CTSO	49FCT805CTSOG
49FCT3805BQI8	49FCT3805BQGI8	49FCT805CTSO8	49FCT805CTSOG8
49FCT3805BSO	49FCT3805BSOG	49FCT805PY	49FCT805PYG
49FCT3805BSO8	49FCT3805BSOG8	49FCT805PY8	49FCT805PYG8
49FCT3805BSOI	49FCT3805BSOGI	49FCT805PYI	49FCT805PYGI
49FCT3805BSOI8	49FCT3805BSOGI8	49FCT805PYI8	49FCT805PYGI8
49FCT3805DPYI	49FCT3805DPYGI	49FCT805SO	49FCT805SOG
49FCT3805DPYI8	49FCT3805DPYGI8	49FCT805SO8	49FCT805SOG8
49FCT3805DQI	49FCT3805DQGI	49FCT805SOI	49FCT805SOGI



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: U-09-01

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
49FCT805SOI8	49FCT805SOGI8	508MI	508MILF
49FCT806APY	49FCT806APYG	508MIT	508MILFT
49FCT806APY8	49FCT806APYG8	508MT	508MLFT
49FCT806ASO	49FCT806ASOG	511M	511MLF
49FCT806ASO8	49FCT806ASOG8	511MI	511MILF
49FCT806BTPY	49FCT806BTPYG	511MIT	511MILFT
49FCT806BTPY8	49FCT806BTPYG8	511MT	511MLFT
49FCT806BTSO	49FCT806BTSOG	512M	512MLF
49FCT806BTSO8	49FCT806BTSOG8	512MI	512MILF
49FCT806CTPY	49FCT806CTPYG	512MIT	512MILFT
49FCT806CTPY8	49FCT806CTPYG8	512MT	512MLFT
49FCT806CTQ	49FCT806CTQG	513M	513MLF
49FCT806CTQ8	49FCT806CTQG8	513MT	513MLFT
49FCT806CTSO	49FCT806CTSOG	514AM	514AMLF
49FCT806CTSO8	49FCT806CTSOG8	514AMT	514AMLFT
49FCT806PY	49FCT806PYG	514M	514MLF
49FCT806PY8	49FCT806PYG8	514MT	514MLFT
49FCT806SO	49FCT806SOG	525-01R	525-01RLF
49FCT806SO8	49FCT806SOG8	525-01RI	525-01RILF
501AM	501AMLF	525-01RIT	525-01RILFT
501AMI	501AMILF	525-01RT	525-01RLFT
501AMIT	501AMILFT	525R-02	525R-02LF
501AMT	501AMLFT	525R-02I	525R-02ILF
501BMI	501BMILF	525R-02IT	525R-02ILFT
501BMIT	501BMILFT	525R-02T	525R-02LFT
501G	501GLF	525R-03I	525R-03ILF
501GI	501GILF	525R-03IT	525R-03ILFT
501GIT	501GILFT	525R-04	525R-04LF
501GT	501GLFT	525R-04T	525R-04LFT
501M	501MLF	525R-11	525R-11LF
501MI	501MILF	525R-11T	525R-11LFT
501MIT	501MILFT	525RI-11	525RI-11LF
501MT	501MLFT	525RI-11T	525RI-11LFT
502M	502MLF	527R-01	527R-01LF
502MI	502MILF	527R-01I	527R-01ILF
502MIT	502MILFT	527R-01IT	527R-01ILFT
502MT	502MLFT	527R-01T	527R-01LFT
503M	503MLF	527R-02	527R-02LF
503MT	503MLFT	527R-02T	527R-02LFT
507M-01	507M-01LF	527R-03	527R-03LF
507M-01I	507M-01ILF	527R-03T	527R-03LFT
507M-01IT	507M-01ILFT	527R-04	527R-04LF
507M-01T	507M-01LFT	527R-04T	527R-04LFT
508M	508MLF	542M	542MLF



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: U-09-01

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
542MI	542MILF	557GI-06T	557GI-06LFT
542MIT	542MILFT	557M-01	557M-01LF
542MT	542MLFT	557M-01T	557M-01LFT
548G-05	548G-05LF	558AG-02	558AG-02LN
548G-05A	548G-05ALF	558AG-02T	558AG-02LNT
548G-05AT	548G-05ALFT	558AG-02T-INO	558AG-02LNT-INO
548G-05T	548G-05LFT	558G-01	558G-01LF
548GI-05A	548GI-05ALF	558G-01T	558G-01LFT
548GI-05AT	548GI-05ALFT	570GI-01	570GI-01LF
551AMI	551AMILF	570GI-01T	570GI-01LFT
551AMIT	551AMILFT	571M	571MLF
551M	551MLF	571MT	571MLFT
551MI	551MILF	574M	574MLF
551MIT	551MILFT	574MI	574MILF
551MT	551MLFT	574MIT	574MILFT
552AR-01	552AR-01LF	574MT	574MLFT
552AR-01T	552AR-01LFT	580M-01	580M-01LF
552ARI-01	552ARI-01LF	580M-01I	580M-01ILF
552ARI-01T	552ARI-01LFT	580M-01IT	580M-01ILFT
552G-02I	552G-02ILN	580M-01T	580M-01LFT
552G-02IT	552G-02ILNT	581G-01	581G-01LF
552R-01	552R-01LN	581G-01I	581G-01ILF
552R-01I	552R-01ILF	581G-01IT	581G-01ILFT
552R-01IT	552R-01ILFT	581G-01T	581G-01LFT
552R-01T	552R-01LNT	581G-02	581G-02LF
553MI	553MILF	581G-02I	581G-02ILF
553MIT	553MILFT	581G-02IT	581G-02ILFT
554G-01AI	554G-01AILF	581G-02T	581G-02LFT
554G-01AIT	554G-01AILFT	5V10004PSI	5V10004PSGI
556G-03I	556G-03ILF	5V10004PSIT	5V10004PSGIT
556G-03IT	556G-03ILFT	5V2305PGI	5V2305PGGI
556M-04I	556M-04ILF	5V2305PGI8	5V2305PGGI8
556M-04IT	556M-04ILFT	5V2310PGI	5V2310PGGI
557G-03	557G-03LF	5V2310PGI8	5V2310PGGI8
557G-03T	557G-03LFT	5V551DCI	5V551DCGI
557G-05A	557G-05ALF	5V551DCI8	5V551DCGI8
557G-05AT	557G-05ALFT	5V9885-003PFI	5V9885-003PFGI
557G-06	557G-06LF	5V9885-003PFI8	5V9885-003PFGI8
557G-06T	557G-06LFT	5V9885B-008PFI	5V9885B-008PFGI
557G-08	557G-08LF	5V9885B-008PFI8	5V9885B-008PFGI8
557G-08T	557G-08LFT	5V9885B-010PFI	5V9885B-010PFGI
557GI-03	557GI-03LF	5V9885B-010PFI8	5V9885B-010PFGI8
557GI-03T	557GI-03LFT	5V9885B-014PFI	5V9885B-014PFGI
557GI-06	557GI-06LF	5V9885B-014PFI8	5V9885B-014PFGI8



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: U-09-01

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
5V9885BPFI	5V9885BPFGI	650G-40AT	650G-40ALFT
5V9885BPFI8	5V9885BPFGI8	650G-40T	650G-40LFT
5V9885CPFI	5V9885CPFGI	650G-43	650G-43LF
5V9885CPFI8	5V9885CPFGI8	650G-43T	650G-43LFT
5V9885PFI	5V9885PFGI	650G-51	650G-51LF
5V9885PFI8	5V9885PFGI8	650G-51T	650G-51LFT
5V9888CPFI	5V9888CPFGI	650GI-41	650GI-41LF
5V9888CPFI8	5V9888CPFGI8	650GI-41T	650GI-41LFT
601G-01	601G-01LF	650GI-44	650GI-44LF
601G-01I	601G-01ILF	650GI-44T	650GI-44LFT
601G-01IT	601G-01ILFT	650M-38	650M-38LF
601G-01T	601G-01LFT	650M-38T	650M-38LFT
601G-21	601G-21LF	650R-01	650R-01LF
601G-21T	601G-21LFT	650R-01I	650R-01ILF
601M-01	601M-01LF	650R-01IT	650R-01ILFT
601M-01I	601M-01ILF	650R-01T	650R-01LFT
601M-01IT	601M-01ILFT	650R-07	650R-07LF
601M-01T	601M-01LFT	650R-07I	650R-07ILF
601M-02I	601M-02ILF	650R-07IT	650R-07ILFT
601M-02IT	601M-02ILFT	650R-07T	650R-07LFT
601R-25	601R-25LF	650R-08	650R-08LF
601R-25I	601R-25ILF	650R-08T	650R-08LFT
601R-25IT	601R-25ILFT	650R-11I	650R-11ILF
601R-25T	601R-25LFT	650R-11IT	650R-11ILFT
612G-01I	612G-01ILF	650R-12	650R-12LF
612G-01IT	612G-01ILFT	650R-12T	650R-12LFT
613M	613MLF	650R-14	650R-14LF
613MT	613MLFT	650R-14I	650R-14ILF
621MI	621MILF	650R-14IT	650R-14ILFT
621MIT	621MILFT	650R-14T	650R-14LFT
623G-03	623G-03LF	650R-21	650R-21LF
623G-03T	623G-03LFT	650R-21I	650R-21ILF
628G-02	628G-02LF	650R-21IT	650R-21ILFT
628G-02T	628G-02LFT	650R-21T	650R-21LFT
633M	633MLF	650R-22	650R-22LF
633MT	633MLFT	650R-22T	650R-22LFT
650F-45	650F-45LF	650R-27I	650R-27ILF
650F-45T	650F-45LFT	650R-27IT	650R-27ILFT
650G-35	650G-35LF	651AMI	651AMILF
650G-35T	650G-35LFT	651AMIT	651AMILFT
650G-36	650G-36LF	651M	651MLF
650G-36T	650G-36LFT	651MI	651MILF
650G-40	650G-40LF	651MIT	651MILFT
650G-40A	650G-40ALF	651MT	651MLFT



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: U-09-01

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
660GI	660GILF	674R-01	674R-01LF
660GIT	660GILFT	674R-01I	674R-01ILF
661GI	661GILF	674R-01IT	674R-01ILFT
661GIT	661GILFT	674R-01T	674R-01LFT
662M-03	662M-03LF	680G-01	680G-01LF
662M-03T	662M-03LFT	680G-01T	680G-01LFT
663M	663MLF	6V49003BPAI	6V49003BPAGI
663MI	663MILF	6V49003BPAI8	6V49003BPAGI8
663MIT	663MILFT	6V49004BPAI	6V49004BPAGI
663MT	663MLFT	6V49004BPAI8	6V49004BPAGI8
664G-01	664G-01LF	7150G	7150GLF
664G-01T	664G-01LFT	7150GT	7150GLFT
664G-02	664G-02LF	7150M	7150MLF
664G-02T	664G-02LFT	7150M-01	7150M-01LF
664G-03	664G-03LF	7150M-01T	7150M-01LFT
664G-03T	664G-03LFT	7150MT	7150MLFT
667M-01	667M-01LF	7151AM-50	7151AM-50LF
667M-01T	667M-01LFT	7151AM-50T	7151AM-50LFT
670M-01	670M-01LF	7151AMI-50	7151AMI-50LF
670M-01I	670M-01ILF	7151AMI-50T	7151AMI-50LFT
670M-01IT	670M-01ILFT	7151M-10	7151M-10LF
670M-01T	670M-01LFT	7151M-10T	7151M-10LFT
670M-02	670M-02LF	7151M-20	7151M-20LF
670M-02T	670M-02LFT	7151M-20T	7151M-20LFT
670M-03I	670M-03ILF	7151M-40	7151M-40LF
670M-03IT	670M-03ILFT	7151M-40T	7151M-40LFT
670M-04I	670M-04ILF	7151M-50	7151M-50LF
670M-04IT	670M-04ILFT	7151M-50T	7151M-50LFT
670MI-02	670MI-02LF	7151MI-10	7151MI-10LF
670MI-02T	670MI-02LFT	7151MI-10T	7151MI-10LFT
671M-01	671M-01LF	7151MI-40	7151MI-40LF
671M-01T	671M-01LFT	7151MI-40T	7151MI-40LFT
671M-03I	671M-03ILF	7152AM-02	7152AM-02LF
671M-03IT	671M-03ILFT	7152AM-02T	7152AM-02LFT
672M-01	672M-01LF	7152AM-11	7152AM-11LF
672M-01T	672M-01LFT	7152AM-11T	7152AM-11LFT
672M-02	672M-02LF	7152AMI-11	7152AMI-11LF
672M-02I	672M-02ILF	7152AMI-11T	7152AMI-11LFT
672M-02IT	672M-02ILFT	7152M-01	7152M-01LF
672M-02T	672M-02LFT	7152M-01T	7152M-01LFT
673M-01	673M-01LF	7152M-02	7152M-02LF
673M-01I	673M-01ILF	7152M-02T	7152M-02LFT
673M-01IT	673M-01ILFT	7152M-11	7152M-11LF
673M-01T	673M-01LFT	7152M-11T	7152M-11LFT



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: U-09-01

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
7152M-12	7152M-12LF	74FCT3807EPGI8	74FCT3807EPGGI8
7152M-12T	7152M-12LFT	74FCT3807EPYI	74FCT3807EPYGI
7152MI-01	7152MI-01LF	74FCT3807EPYI8	74FCT3807EPYGI8
7152MI-01T	7152MI-01LFT	74FCT3807EQI	74FCT3807EQGI
7152MI-11	7152MI-11LF	74FCT3807EQI8	74FCT3807EQGI8
7152MI-11T	7152MI-11LFT	74FCT3807PY	74FCT3807PYG
7152MI-12	7152MI-12LF	74FCT3807PY8	74FCT3807PYG8
7152MI-12T	7152MI-12LFT	74FCT3807PYI	74FCT3807PYGI
722M	722MLF	74FCT3807PYI8	74FCT3807PYGI8
722MT	722MLFT	74FCT3807Q	74FCT3807QG
728M	728MLF	74FCT3807Q8	74FCT3807QG8
728MT	728MLFT	74FCT3807QI	74FCT3807QGI
74CB218AR	74CB218ARLF	74FCT3807QI8	74FCT3807QGI8
74CB218ARTR	74CB218ARLFT	74FCT3807SO	74FCT3807SOG
74CB218CR	74CB218CRLF	74FCT3807SO8	74FCT3807SOG8
74FCT20807PYI	74FCT20807PYGI	74FCT3807SOI	74FCT3807SOGI
74FCT20807PYI8	74FCT20807PYGI8	74FCT3807SOI8	74FCT3807SOGI8
74FCT20807QI	74FCT20807QGI	74FCT3811PYI	74FCT3811PYGI
74FCT20807QI8	74FCT20807QGI8	74FCT3811PYI8	74FCT3811PYGI8
74FCT38072DCI	74FCT38072DCGI	74FCT807BTPY	74FCT807BTPYG
74FCT38072DCI8	74FCT38072DCGI8	74FCT807BTPY8	74FCT807BTPYG8
74FCT38074DCI	74FCT38074DCGI	74FCT807BTPYI	74FCT807BTPYGI
74FCT38074DCI8	74FCT38074DCGI8	74FCT807BTPYI8	74FCT807BTPYGI8
74FCT38075DCI	74FCT38075DCGI	74FCT807BTQ	74FCT807BTQG
74FCT38075DCI8	74FCT38075DCGI8	74FCT807BTQ8	74FCT807BTQG8
74FCT3807APY	74FCT3807APYG	74FCT807BTQI	74FCT807BTQGI
74FCT3807APY8	74FCT3807APYG8	74FCT807BTQI8	74FCT807BTQGI8
74FCT3807APYI	74FCT3807APYGI	74FCT807BTSO	74FCT807BTSOG
74FCT3807APYI8	74FCT3807APYGI8	74FCT807BTSO8	74FCT807BTSOG8
74FCT3807AQ	74FCT3807AQG	74FCT807BTSOI	74FCT807BTSOGI
74FCT3807AQ8	74FCT3807AQG8	74FCT807BTSOI8	74FCT807BTSOGI8
74FCT3807AQI	74FCT3807AQGI	74FCT807CTPY	74FCT807CTPYG
74FCT3807AQI8	74FCT3807AQGI8	74FCT807CTPY8	74FCT807CTPYG8
74FCT3807ASO	74FCT3807ASOG	74FCT807CTPYI	74FCT807CTPYGI
74FCT3807ASO8	74FCT3807ASOG8	74FCT807CTPYI8	74FCT807CTPYGI8
74FCT3807ASOI	74FCT3807ASOGI	74FCT807CTQ	74FCT807CTQG
74FCT3807ASOI8	74FCT3807ASOGI8	74FCT807CTQ8	74FCT807CTQG8
74FCT3807DPGI	74FCT3807DPGGI	74FCT807CTQI	74FCT807CTQGI
74FCT3807DPGI8	74FCT3807DPGGI8	74FCT807CTQI8	74FCT807CTQGI8
74FCT3807DPYI	74FCT3807DPYGI	74FCT807CTSO	74FCT807CTSOG
74FCT3807DPYI8	74FCT3807DPYGI8	74FCT807CTSO8	74FCT807CTSOG8
74FCT3807DQI	74FCT3807DQGI	74FCT807CTSOI	74FCT807CTSOGI
74FCT3807DQI8	74FCT3807DQGI8	74FCT807CTSOI8	74FCT807CTSOGI8
74FCT3807EPGI	74FCT3807EPGGI	74FCT810BTPY	74FCT810BTPYG



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: U-09-01

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
74FCT810BTPY8	74FCT810BTPYG8	MK1704ATR	MK1704ALFTR
74FCT810BTQ	74FCT810BTQG	MK1707SI	MK1707SILF
74FCT810BTQ8	74FCT810BTQG8	MK1707SITR	MK1707SILFTR
74FCT810BTSO	74FCT810BTSOG	MK1709AG	MK1709AGLF
74FCT810BTSO8	74FCT810BTSOG8	MK1709AGT	MK1709AGLFTR
74FCT810CTPY	74FCT810CTPYG	MK1709S	MK1709SLF
74FCT810CTPY8	74FCT810CTPYG8	MK1709STR	MK1709SLFTR
74FCT810CTQ	74FCT810CTQG	MK1714-01R	MK1714-01RLF
74FCT810CTQ8	74FCT810CTQG8	MK1714-01RI	MK1714-01RILF
74FCT810CTSO	74FCT810CTSOG	MK1714-01RITR	MK1714-01RILFTR
74FCT810CTSO8	74FCT810CTSOG8	MK1714-01RTR	MK1714-01RLFTR
9112CM-18	9112CM-18LF	MK1714-02R	MK1714-02RLF
9112CM-18T	9112CM-18LFT	MK1714-02RI	MK1714-02RILF
LV810FI	LV810FILF	MK1714-02RIT	MK1714-02RILFTR
LV810FIT	LV810FILFT	MK1714-02RTR	MK1714-02RLFTR
LV810RI	LV810RILF	MK1716-01R	MK1716-01RLF
LV810RIT	LV810RILFT	MK1716-01RTR	MK1716-01RLFTR
MK1413S	MK1413SLF	MK1726-01S	MK1726-01SLF
MK1413STR	MK1413SLFTR	MK1726-01STR	MK1726-01SLFTR
MK1491-06R	MK1491-06RLF	MK1726-08S	MK1726-08SLF
MK1491-06RTR	MK1491-06RLFTR	MK1726-08STR	MK1726-08SLFTR
MK1491-06S	MK1491-06SLF	MK1727-01DGI	MK1727-01DGILF
MK1491-06STR	MK1491-06SLFTR	MK1727-01DGITR	MK1727-01DGILFTR
MK1491-09F	MK1491-09FLN	MK1728-01S	MK1728-01SLF
MK1491-09FTR	MK1491-09FLNTR	MK1728-01STR	MK1728-01SLFTR
MK1491E-14R	MK1491E-14RLF	MK2049-34SAI	MK2049-34SAILF
MK1491E-14RTR	MK1491E-14RLFTR	MK2049-34SAITR	MK2049-34SAILFTR
MK1493-03BG	MK1493-03BGLF	MK2049-36SI	MK2049-36SILF
MK1493-03BGTR	MK1493-03BGLFTR	MK2049-36SITR	MK2049-36SILFTR
MK1493-05G	MK1493-05GLF	MK2049-45ASI	MK2049-45ASILF
MK1493-05GTR	MK1493-05GLFTR	MK2049-45ASITR	MK2049-45ASILFTR
MK1574-01BSI	MK1574-01BSILF	MK2049-45SI	MK2049-45SILF
MK1574-01BSITR	MK1574-01BSILFTR	MK2049-45SITR	MK2049-45SILFTR
MK1574-01S	MK1574-01SLF	MK2058-01SI	MK2058-01SILF
MK1574-01SI	MK1574-01SILF	MK2058-01SITR	MK2058-01SILFTR
MK1574-01SITR	MK1574-01SILFTR	MK2059-01SI	MK2059-01SILF
MK1574-01STR	MK1574-01SLFTR	MK2059-01SITR	MK2059-01SILFTR
MK1575-01G	MK1575-01GLF	MK2069-01GI	MK2069-01GILF
MK1575-01GI	MK1575-01GILF	MK2069-01GITR	MK2069-01GILFTR
MK1575-01GITR	MK1575-01GILFTR	MK2069-04GI	MK2069-04GILF
MK1575-01GTR	MK1575-01GLFTR	MK2069-04GITR	MK2069-04GILFTR
MK1581-01GI	MK1581-01GILF	MK2302S-01	MK2302S-01LF
MK1581-01GITR	MK1581-01GILFTR	MK2302S-01TR	MK2302S-01LFTR
MK1704A	MK1704ALF	MK2304S-2	MK2304S-2LF



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: U-09-01

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
MK2304S-2TR	MK2304S-2LFTR	MK2771-15R	MK2771-15RLF
MK2308G-1H	MK2308G-1HLF	MK2771-15RTR	MK2771-15RLFTR
MK2308G-1HI	MK2308G-1HILF	MK2771-16R	MK2771-16RLF
MK2308G-1HITR	MK2308G-1HILFTR	MK2771-16RTR	MK2771-16RLFTR
MK2308G-1HTR	MK2308G-1HLFTR	MK2772-01S	MK2772-01SLF
MK2308S-1H	MK2308S-1HLF	MK2772-01STR	MK2772-01SLFTR
MK2308S-1HI	MK2308S-1HILF	MK3200S	MK3200SLF
MK2308S-1HITR	MK2308S-1HILFTR	MK3200SI	MK3200SILF
MK2308S-1HTR	MK2308S-1HLFTR	MK3200SITR	MK3200SILFTR
MK2308S-2	MK2308S-2LF	MK3200STR	MK3200SLFTR
MK2308S-2I	MK2308S-2ILF	MK3711DM	MK3711DMILF
MK2308S-2TR	MK2308S-2LFTR	MK3711DMI	MK3711DMILF
MK2703S	MK2703SLF	MK3722G	MK3722GLF
MK2703SI	MK2703SILF	MK3722GTR	MK3722GLFTR
MK2703SITR	MK2703SILFTR	MK3724G	MK3724GLF
MK2703STR	MK2703SLFTR	MK3724GTR	MK3724GLFTR
MK2704S	MK2704SLF	MK3727H	MK3727HLF
MK2704STR	MK2704SLFTR	MK3727HTR	MK3727HLFTR
MK2705S	MK2705SLF	MK3732-10S	MK3732-10SLF
MK2705STR	MK2705SLFTR	MK3732-10STR	MK3732-10SLFTR
MK2712S	MK2712SLF	MK3732-19G	MK3732-19GLF
MK2712STR	MK2712SLFTR	MK3732-19GTR	MK3732-19GLFTR
MK2716S	MK2716SLF	MK3732-23R	MK3732-23RLF
MK2716STR	MK2716SLFTR	MK3732-23RTR	MK3732-23RLFTR
MK2727S	MK2727SLF	MK3732-25BF	MK3732-25BFLF
MK2727STR	MK2727SLFTR	MK3734S	MK3734SLF
MK2732-06G	MK2732-06GLF	MK3734STR	MK3734SLFTR
MK2732-06GTR	MK2732-06GLFTR	MK3741S	MK3741SLF
MK2745-21S	MK2745-21SLF	MK3741STR	MK3741SLFTR
MK2745-21STR	MK2745-21SLFTR	MK3771-17R	MK3771-17RLF
MK2745-24S	MK2745-24SLF	MK3771-17RTR	MK3771-17RLFTR
MK2745-24STR	MK2745-24SLFTR	MK3805RI	MK3805RILF
MK2745-26S	MK2745-26SLF	MK3805RITR	MK3805RILFTR
MK2745-26STR	MK2745-26SLFTR	MK3807-01RI	MK3807-01RILF
MK2745-28BR	MK2745-28BRLF	MK3807-01RITR	MK3807-01RILFTR
MK2745-28BRTR	MK2745-28BRLFTR	MK5811S	MK5811SLF
MK2745-33G	MK2745-33GLF	MK5811STR	MK5811SLFTR
MK2745-33GTR	MK2745-33GLFTR	MK5812S	MK5812SLF
MK2746-01G	MK2746-01GLF	MK5812STR	MK5812SLFTR
MK2746-01GTR	MK2746-01GLFTR	MK5814G	MK5814GLF
MK2746G	MK2746GLF	MK5814GTR	MK5814GLFTR
MK2746GTR	MK2746GLFTR	MK5814S	MK5814SLF
MK2761AS	MK2761ASLF	MK5814STR	MK5814SLFTR
MK2761ASTR	MK2761ASLFTR	MK5818S	MK5818SLF



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: U-09-01

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
MK5818STR	MK5818SLFTR	MK74CG117BFTR	MK74CG117BFLFTR
MK712R	MK712RLF	MK9170-01CS08	MK9170-01CS08LF
MK712RTR	MK712RLFTR	MK9170-01CS08T	MK9170-01CS08LFTR
MK712RW	MK712RWLF	MK9170-02CS08	MK9170-02CS08LF
MK712RWTR	MK712RWLFTR	MK9170-02CS08T	MK9170-02CS08LFT
MK712S	MK712SLF	MK9170-05CS08	MK9170-05CS08LF
MK712STR	MK712SLFTR	MK9170-05CS08T	MK9170-05CS08LFT
MK74CB218BR	MK74CB218BRLF	MK9173-01CS08	MK9173-01CS08LF
MK74CB218BRTR	MK74CB218BRLFTR	MK9173-01CS08T	MK9173-01CS08LFT
MK74CB218R	MK74CB218RLF	MK9173-15CS08	MK9173-15CS08LF
MK74CB218RTR	MK74CB218RLFTR	MK9173-15CS08T	MK9173-15CS08LFT
MK74CB44R	MK74CB44RLF	NIS/RC-872	NIS/RC-872LF
MK74CB44RTR	MK74CB44RLFTR	NIS/RC-872TR	NIS/RC-872LFTR
MK74CG117BF	MK74CG117BFLF		