

Customer Information Notification

Issue Date: 19-Sep-2014 Effective Date: 01-Oct-2014

Here's your personalized quality information concerning products Digi-Key purchased from NXP. For detailed information we invite you to view this notification online



Management Summary

PCAL6416AEX Top Side marking improvement.

Change Category

[] Wafer Fab process[] Assembly Process[X] Product Marking[] Wafer Fab[] Assembly[] Electrical spec./TestmaterialsMaterialscoverage[] Wafer Fab location[] Assembly Location[] Test Location

[] Design [] Mechanical Specification

[] Packing/Shipping/Labeling

PCAL6416AEX Top Side marking improvement

Information Notification

Introduce a top side marking improvement by implementing a minor modification.

Current topside marking of the PCAL6416AEX is L16. - Bar codes exist on the package to provide indication of Year and Month.

To better align with other packages in the family and provide improved traceability, the marking will be enhanced with a minor modification.

Where the current marking (as of Sept 2014) uses a non-changing 'L16', the improved version will use the format as indicated L6[W].

Improved marking will use the same bar coding for Year and Month coding, but will have the Part Type truncated to two chars (L6)

allowing NXP to incorporate a rotating 3rd char as seen in the [W] position. The W will represent the Week number of the NXP Month

and as such rotate through the weeks of the month (1-5), providing an improved level of traceability

Why do we issue this Information Notification Provide the customer and NXP with improved traceability. Identification of Affected Products Top side marking Impact

no impact to the product's functionality anticipated.

Data Sheet Revision A new datasheet will be issued Disposition of Old Products Existing inventory will be shipped until depleted

Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:NameDavid BannonPositionQuality Manager BL Interface Solutions - HSIe-mail addressdavid.bannon@nxp.com

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards. Customer Focus, Passion to Win.

NXP Quality Management Team.

About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP's Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

NYD Privray Paliay Torma of Llaa

NXP | Privacy Policy | Terms of Use

NXP Semiconductors

High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006-2010 NXP Semiconductors. All rights reserved.