

<b>PCN Number:</b>	20170921004	<b>PCN Date:</b>	September 22, 2017
<b>Title:</b>	Datasheet for TUSB3410, TUSB3410I		
<b>Customer Contact:</b>	<a href="#">PCN Manager</a>	<b>Dept:</b>	Quality Services
<b>Change Type:</b>			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

### Notification Details

#### Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.



**TUSB3410, TUSB3410I**

SLLS519J – MARCH 2002 – REVISED JULY 2017

#### Changes from Revision I (November 2015) to Revision J

Page

- Changed pin 21 From: DTR To: active low DTR in the *Pin Functions* table ..... [5](#)
- Changed the description of bit 7 CONT in *USBCTL: USB Control Register (Addr:FFFCh)*, CONT= 0 From: enabled To: disabled, CONT= 1 From: disabled To: enabled ..... [40](#)

The datasheet number will be changing.

Device Family	Change From:	Change To:
TUSB3410, TUSB3410I	SLLS519I	SLLS519J

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/TUSB3410>

#### Reason for Change:

To accurately reflect device characteristics.

#### Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

#### Changes to product identification resulting from this PCN:

None.

#### Product Affected:

TUSB3410IRHB	TUSB3410IRHBR	TUSB3410IRHBRG4	TUSB3410IRHBT
TUSB3410IVF	TUSB3410IVFG4	TUSB3410RHB	TUSB3410RHBG4
TUSB3410RHBR	TUSB3410RHBT	TUSB3410VF	TUSB3410VFG4

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>