



# Product Change Notification

## TE Connectivity

Product Change Notification: P-17-015058

PCN Date: 14-NOV-17

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:  
AFFECTS CUSTOMER SHIPMENTS WITHIN NORTH AMERICA ONLY - Distribution Center change from Mechanicsburg, PA to El Paso, TX

Description of Changes THERE IS NO CHANGE TO MANUFACTURING LOCATION OR TO PARTS! Due to consolidation of Distribution Centers, TE is moving the material from our Pennsylvania DC in Mechanicsburg, PA to our DC in El Paso, TX. The transition to El Paso will take place during the weekend of January 20th, 2018. All products you currently receive from our Mechanicsburg, PA location will be transitioned to the new Distribution Center by Monday, January 22nd, 2018. In preparation of the January 23rd go-live, TE will be shipping January 22nd requirements on Friday January 19th, 2018. Your TE Customer Care Representative will contact you to review any special arrangements required for pick-up on Friday and to make any appropriate adjustments to your DUNS/Vendor Codes/Supplier Codes for the new DC. Current DC address: 1311 S. Market Street, Mechanicsburg, PA 17055 Current DUNS Code: 781582481 New DC address: 32 Celerity Wagon, El Paso, TX 79906 New DUNS Code: 080037706 See attached Customer Notification letter. Other attachments:  
[Customer Notification Letter](#)

Reason for Changes: Customer Request.Consolidation of distribution centers. Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only): 23-JAN-2018
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only): No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1355154-1</a>	NO						
<a href="#">1-1355668-2</a>	NO						
<a href="#">1-1393277-4</a>	NO			"V23076A3001C132"			
<a href="#">1-1414939-4</a>	NO						
<a href="#">1-1418448-1</a>	NO			"8202607143"			
<a href="#">1-1418479-1</a>	NO						
<a href="#">1-1418480-1</a>	NO						
<a href="#">1-1418497-0</a>	NO						
<a href="#">1-1418775-1</a>	NO						
<a href="#">1-1534155-1</a>	NO						
<a href="#">1-1719506-3</a>	NO						
<a href="#">1-1904045-2</a>	NO			"3 334 485 008", "V23333-Z1001-A008"			
<a href="#">1-1904045-5</a>	NO			"3 334 485 045", "V23333-Z1001-B045"			
<a href="#">1-1904045-6</a>	NO			"3 334 485 046", "V23333-Z0001-B046"			
<a href="#">1-929504-1</a>	NO						
<a href="#">1-962841-2</a>	NO						
<a href="#">1-962915-3</a>	NO						
<a href="#">1-962916-2</a>	NO						
<a href="#">1-963215-1</a>	NO						
<a href="#">1-963449-2</a>	NO						
<a href="#">1-964294-3</a>	NO						
<a href="#">1-964300-3</a>	NO						
<a href="#">1-967240-1</a>	NO						
<a href="#">1-967281-1</a>	NO						
<a href="#">1-967623-6</a>	NO						
<a href="#">1-967624-1</a>	NO						
<a href="#">1-967626-1</a>	NO						
<a href="#">1-968849-2</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">100283-1</a>	NO						
<a href="#">100291-1</a>	NO						
<a href="#">106462-1</a>	NO						
<a href="#">1241434-1</a>	NO						
<a href="#">1241634-3</a>	NO						
<a href="#">1337352-1</a>	NO						
<a href="#">1355206-1</a>	NO						
<a href="#">1355526-2</a>	NO						
<a href="#">1379118-1</a>	NO						
<a href="#">1379217-1</a>	NO						
<a href="#">1379675-1</a>	NO						
<a href="#">1393276-7</a>	NO			"V23071A1010A132"			
<a href="#">1393277-8</a>	NO			"V23076A1022C133"			
<a href="#">1393280-5</a>	NO			"V23086C1001A402"			
<a href="#">1393304-9</a>	NO			"V23134J1052D642"			
<a href="#">1393315-2</a>	NO			"V23132A2001A200"			
<a href="#">1393315-9</a>	NO			"V23132B2002A200"			
<a href="#">1418884-3</a>	NO						
<a href="#">1418994-1</a>	NO						
<a href="#">144617-1</a>	NO						
<a href="#">144969-2</a>	NO						
<a href="#">1452601-1</a>	NO						
<a href="#">1534046-1</a>	NO						
<a href="#">1544332-1</a>	NO			"P790861"			
<a href="#">1544333-1</a>	NO			"P790862"			
<a href="#">1544545-3</a>	NO			"P7310073060"			
<a href="#">1563110-1</a>	NO						
<a href="#">166500-2</a>	NO						
<a href="#">1670364-1</a>	NO						
<a href="#">1670365-1</a>	NO						
<a href="#">172500-1</a>	NO						
<a href="#">183035-1</a>	NO			"CM8391-000", "AMP-0-0183035-1", "2-42939-6221", "820P-36547", "4004200209"			
<a href="#">1904000-1</a>	NO			"0 332 002 150"			
<a href="#">2-1355123-3</a>	NO						
<a href="#">2-1393302-2</a>	NO			"V23134A 52C643", "V23134A0052C643", "D33228-000", "AMPS-2-1393302-2"			
<a href="#">2-1904025-6</a>	NO			"0 332 209 211"			
<a href="#">2-1904045-4</a>	NO			"3 334 485 041", "V23333-Z0002-A041"			
<a href="#">2-1904058-5</a>	NO			"V23700-C0001-A408"			
<a href="#">2-1904058-7</a>	NO			"V23700-F0002-A408"			
<a href="#">2-1904070-2</a>	NO						
<a href="#">2-962915-1</a>	NO						
<a href="#">2-963217-1</a>	NO						
<a href="#">2-967059-1</a>	NO						
<a href="#">281934-3</a>	NO			"80.246.00"			
<a href="#">282080-2</a>	NO						
<a href="#">282107-1</a>	NO						
<a href="#">282109-1</a>	NO						
<a href="#">282189-1</a>	NO			"CF0543-000", "AMP-0-0282189-1"			
<a href="#">282191-1</a>	NO						
<a href="#">282308-1</a>	NO						
<a href="#">282404-1</a>	NO			"61.355.00", "820P-36528"			
<a href="#">282465-1</a>	NO			"61.359.00"			
<a href="#">282466-1</a>	NO			"EG9735-000", "AMP-0-0282466-1"			
<a href="#">284617-1</a>	NO						
<a href="#">3-1393278-7</a>	NO			"V23133A1022C133"			
<a href="#">3-1393292-8</a>	NO			"V23074A1002A403"			
<a href="#">3-1393303-4</a>	NO			"V23134B1052C642"			
<a href="#">3-1393303-7</a>	NO			"V23134B1053C642"			
<a href="#">3-1418390-1</a>	NO						
<a href="#">344009-1</a>	NO						
<a href="#">344106-1</a>	NO						
<a href="#">344108-1</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">345809-1</a>	NO						
<a href="#">4-1904065-7</a>	NO						
<a href="#">4-1904124-3</a>	NO						
<a href="#">5-1393302-1</a>	NO			"V23134A 53C643"			
<a href="#">5-1393302-8</a>	NO			"V23134A1052C643"			
<a href="#">6-1393292-3</a>	NO			"V23074A2002A403"			
<a href="#">6-968974-1</a>	NO						
<a href="#">7-1414967-8</a>	NO			"V23086-R1802-A803"			
<a href="#">7-1452671-3</a>	NO						
<a href="#">8-1393305-7</a>	NO			"VF4-55F11-S01"			
<a href="#">827551-3</a>	NO			"CF0027-000", "AMP-0-0827551-3"			
<a href="#">828801-4</a>	NO						
<a href="#">828801-5</a>	NO						
<a href="#">880811-2</a>	NO			"EG9729-000", "AMP-0-0880811-2", "51.033.00"			
<a href="#">9-1452380-9</a>	NO						
<a href="#">9-1563172-9</a>	NO						
<a href="#">9-1563173-9</a>	NO						
<a href="#">9-965382-2</a>	NO						
<a href="#">925590-2</a>	NO			"0-0925590-2"			
<a href="#">927766-3</a>	NO			"AMP-0-0927766-3", "E17312-000"			
<a href="#">927768-9</a>	NO						
<a href="#">927773-3</a>	NO						
<a href="#">929027-3</a>	NO						
<a href="#">929387-1</a>	NO						
<a href="#">929504-1</a>	NO						
<a href="#">929504-2</a>	NO						
<a href="#">929504-3</a>	NO						
<a href="#">929504-4</a>	NO						
<a href="#">929504-5</a>	NO						
<a href="#">929504-6</a>	NO						
<a href="#">929650-2</a>	NO						
<a href="#">929968-1</a>	NO						
<a href="#">929971-1</a>	NO						
<a href="#">929989-1</a>	NO						
<a href="#">929990-1</a>	NO						
<a href="#">962189-1</a>	NO						
<a href="#">962191-1</a>	NO						
<a href="#">963216-1</a>	NO						
<a href="#">963357-5</a>	NO						
<a href="#">963598-1</a>	NO						
<a href="#">963774-1</a>	NO						
<a href="#">963904-3</a>	NO						
<a href="#">965601-2</a>	NO						
<a href="#">965643-1</a>	NO						
<a href="#">965901-1</a>	NO						
<a href="#">967598-1</a>	NO						
<a href="#">968271-1</a>	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1355668-2</a>	NO						
<a href="#">1-1393277-4</a>	NO			"V23076A3001C132"			
<a href="#">1-1414939-4</a>	NO						
<a href="#">1-1418480-1</a>	NO						
<a href="#">1-1418497-0</a>	NO						
<a href="#">1-1904045-2</a>	NO			"3 334 485 008", "V23333-Z1001-A008"			
<a href="#">1-1904045-5</a>	NO			"3 334 485 045", "V23333-Z1001-B045"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1904045-6</a>	NO			"3 334 485 046", "V23333-Z0001-B046"			
<a href="#">1-929504-1</a>	NO						
<a href="#">1-962841-2</a>	NO						
<a href="#">1-962915-3</a>	NO						
<a href="#">1-962916-2</a>	NO						
<a href="#">1-963215-1</a>	NO						
<a href="#">1-963449-2</a>	NO						
<a href="#">1-967240-1</a>	NO						
<a href="#">1-967281-1</a>	NO						
<a href="#">1-967624-1</a>	NO						
<a href="#">1-967626-1</a>	NO						
<a href="#">100283-1</a>	NO						
<a href="#">100291-1</a>	NO						
<a href="#">106462-1</a>	NO						
<a href="#">1241434-1</a>	NO						
<a href="#">1355206-1</a>	NO						
<a href="#">1379217-1</a>	NO						
<a href="#">1393276-7</a>	NO			"V23071A1010A132"			
<a href="#">1393277-8</a>	NO			"V23076A1022C133"			
<a href="#">1393280-5</a>	NO			"V23086C1001A402"			
<a href="#">1393304-9</a>	NO			"V23134J1052D642"			
<a href="#">1393315-2</a>	NO			"V23132A2001A200"			
<a href="#">1393315-9</a>	NO			"V23132B2002A200"			
<a href="#">1418994-1</a>	NO						
<a href="#">144617-1</a>	NO						
<a href="#">144969-2</a>	NO						
<a href="#">1452601-1</a>	NO						
<a href="#">1534046-1</a>	NO						
<a href="#">1544332-1</a>	NO			"P790861"			
<a href="#">1544545-3</a>	NO			"P7310073060"			
<a href="#">172500-1</a>	NO						
<a href="#">183035-1</a>	NO			"CM8391-000", "AMP-0-0183035-1", "2-42939-6221", "820P-36547", "4004200209"			
<a href="#">1904000-1</a>	NO			"0 332 002 150"			
<a href="#">2-1393302-2</a>	NO			"V23134A 52C643", "V23134A0052C643", "D33228-000", "AMPS-2-1393302-2"			
<a href="#">2-1904025-6</a>	NO			"0 332 209 211"			
<a href="#">2-1904045-4</a>	NO			"3 334 485 041", "V23333-Z0002-A041"			
<a href="#">2-1904058-5</a>	NO			"V23700-C0001-A408"			
<a href="#">2-1904058-7</a>	NO			"V23700-F0002-A408"			
<a href="#">2-1904070-2</a>	NO						
<a href="#">2-962915-1</a>	NO						
<a href="#">2-963217-1</a>	NO						
<a href="#">2-967059-1</a>	NO						
<a href="#">281934-3</a>	NO			"80.246.00"			
<a href="#">282107-1</a>	NO						
<a href="#">282109-1</a>	NO						
<a href="#">282191-1</a>	NO						
<a href="#">282308-1</a>	NO						
<a href="#">282404-1</a>	NO			"61.355.00", "820P-36528"			
<a href="#">282465-1</a>	NO			"61.359.00"			
<a href="#">282466-1</a>	NO			"EG9735-000", "AMP-0-0282466-1"			
<a href="#">284617-1</a>	NO						
<a href="#">3-1393278-7</a>	NO			"V23133A1022C133"			
<a href="#">3-1393292-8</a>	NO			"V23074A1002A403"			
<a href="#">3-1393303-4</a>	NO			"V23134B1052C642"			
<a href="#">3-1393303-7</a>	NO			"V23134B1053C642"			
<a href="#">344106-1</a>	NO						
<a href="#">344108-1</a>	NO						
<a href="#">4-1904065-7</a>	NO						
<a href="#">4-1904124-3</a>	NO						
<a href="#">5-1393302-1</a>	NO			"V23134A 53C643"			
<a href="#">5-1393302-8</a>	NO			"V23134A1052C643"			
<a href="#">6-1393292-3</a>	NO			"V23074A2002A403"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">7-1414967-8</a>	NO			"V23086-R1802-A803"			
<a href="#">8-1393305-7</a>	NO			"VF4-55F11-S01"			
<a href="#">827551-3</a>	NO			"CF0027-000", "AMP-0-0827551-3"			
<a href="#">828801-5</a>	NO						
<a href="#">880811-2</a>	NO			"EG9729-000", "AMP-0-0880811-2", "51.033.00"			
<a href="#">925590-2</a>	NO			"0-0925590-2"			
<a href="#">927766-3</a>	NO			"AMP-0-0927766-3", "E17312-000"			
<a href="#">927773-3</a>	NO						
<a href="#">929504-1</a>	NO						
<a href="#">929504-5</a>	NO						
<a href="#">929504-6</a>	NO						
<a href="#">929968-1</a>	NO						
<a href="#">929989-1</a>	NO						
<a href="#">929990-1</a>	NO						
<a href="#">962189-1</a>	NO						
<a href="#">962191-1</a>	NO						
<a href="#">963216-1</a>	NO						
<a href="#">963357-5</a>	NO						
<a href="#">963598-1</a>	NO						
<a href="#">965643-1</a>	NO						
<a href="#">965901-1</a>	NO						
<a href="#">968271-1</a>	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1355668-2</a>	NO						
<a href="#">1-1393277-4</a>	NO			"V23076A3001C132"			
<a href="#">1-1414939-4</a>	NO						
<a href="#">1-1418480-1</a>	NO						
<a href="#">1-1418497-0</a>	NO						
<a href="#">1-1904045-2</a>	NO			"3 334 485 008", "V23333-Z1001-A008"			
<a href="#">1-1904045-8</a>	NO			"3 334 485 045", "V23333-Z1001-B045"			
<a href="#">1-1904045-6</a>	NO			"3 334 485 046", "V23333-Z0001-B046"			
<a href="#">1-929504-1</a>	NO						
<a href="#">1-962841-2</a>	NO						
<a href="#">1-962915-3</a>	NO						
<a href="#">1-962916-2</a>	NO						
<a href="#">1-963215-1</a>	NO						
<a href="#">1-963449-2</a>	NO						
<a href="#">1-967240-1</a>	NO						
<a href="#">1-967281-1</a>	NO						
<a href="#">1-967624-1</a>	NO						
<a href="#">1-967626-1</a>	NO						
<a href="#">100283-1</a>	NO						
<a href="#">100291-1</a>	NO						
<a href="#">106462-1</a>	NO						
<a href="#">1241434-1</a>	NO						
<a href="#">1355206-1</a>	NO						
<a href="#">1379217-1</a>	NO						
<a href="#">1393276-7</a>	NO			"V23071A1010A132"			
<a href="#">1393277-8</a>	NO			"V23076A1022C133"			
<a href="#">1393280-5</a>	NO			"V23086C1001A402"			
<a href="#">1393304-9</a>	NO			"V23134J1052D642"			
<a href="#">1393315-2</a>	NO			"V23132A2001A200"			
<a href="#">1393315-9</a>	NO			"V23132B2002A200"			
<a href="#">1418994-1</a>	NO						
<a href="#">144617-1</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">144969-2</a>	NO						
<a href="#">1452601-1</a>	NO						
<a href="#">1534046-1</a>	NO						
<a href="#">1544332-1</a>	NO			"P790861"			
<a href="#">1544545-3</a>	NO			"P7310073060"			
<a href="#">172500-1</a>	NO						
<a href="#">183035-1</a>	NO			"CM8391-000", "AMP-0-0183035-1", "2-42939-6221", "820P-36547", "4004200209"			
<a href="#">1904000-1</a>	NO			"0 332 002 150"			
<a href="#">2-1393302-2</a>	NO			"V23134A 52C643", "V23134A0052C643", "D33228-000", "AMPS-2-1393302-2"			
<a href="#">2-1904025-6</a>	NO			"0 332 209 211"			
<a href="#">2-1904045-4</a>	NO			"3 334 485 041", "V23333-Z0002-A041"			
<a href="#">2-1904058-5</a>	NO			"V23700-C0001-A408"			
<a href="#">2-1904058-7</a>	NO			"V23700-F0002-A408"			
<a href="#">2-1904070-2</a>	NO						
<a href="#">2-962915-1</a>	NO						
<a href="#">2-963217-1</a>	NO						
<a href="#">2-967059-1</a>	NO						
<a href="#">281934-3</a>	NO			"80.246.00"			
<a href="#">282107-1</a>	NO						
<a href="#">282109-1</a>	NO						
<a href="#">282191-1</a>	NO						
<a href="#">282308-1</a>	NO						
<a href="#">282404-1</a>	NO			"61.355.00", "820P-36528"			
<a href="#">282465-1</a>	NO			"61.359.00"			
<a href="#">282466-1</a>	NO			"EG9735-000", "AMP-0-0282466-1"			
<a href="#">284617-1</a>	NO						
<a href="#">3-1393278-7</a>	NO			"V23133A1022C133"			
<a href="#">3-1393292-5</a>	NO			"V23074A1002A403"			
<a href="#">3-1393303-7</a>	NO			"V23134B1053C642"			
<a href="#">344106-1</a>	NO						
<a href="#">344108-1</a>	NO						
<a href="#">4-1904065-7</a>	NO						
<a href="#">4-1904124-3</a>	NO						
<a href="#">5-1393302-1</a>	NO			"V23134A 53C643"			
<a href="#">5-1393302-8</a>	NO			"V23134A1052C643"			
<a href="#">6-1393292-3</a>	NO			"V23074A2002A403"			
<a href="#">7-1414967-5</a>	NO			"V23086-R1802-A803"			
<a href="#">8-1393305-7</a>	NO			"VF4-55F11-S01"			
<a href="#">827551-3</a>	NO			"CF0027-000", "AMP-0-0827551-3"			
<a href="#">828801-5</a>	NO						
<a href="#">880811-2</a>	NO			"EG9729-000", "AMP-0-0880811-2", "51.033.00"			
<a href="#">925590-2</a>	NO			"0-0925590-2"			
<a href="#">927766-3</a>	NO			"AMP-0-0927766-3", "E17312-000"			
<a href="#">927773-3</a>	NO						
<a href="#">929504-1</a>	NO						
<a href="#">929504-5</a>	NO						
<a href="#">929504-6</a>	NO						
<a href="#">929968-1</a>	NO						
<a href="#">929989-1</a>	NO						
<a href="#">929990-1</a>	NO						
<a href="#">962189-1</a>	NO						
<a href="#">962191-1</a>	NO						
<a href="#">963216-1</a>	NO						
<a href="#">963357-5</a>	NO						
<a href="#">963598-1</a>	NO						
<a href="#">965643-1</a>	NO						
<a href="#">965901-1</a>	NO						
<a href="#">968271-1</a>	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1355154-1</a>	NO						
<a href="#">1-1418448-1</a>	NO			"8202607143"			
<a href="#">1-1418479-1</a>	NO						
<a href="#">1-1418480-1</a>	NO						
<a href="#">1-1418775-1</a>	NO						
<a href="#">1-1534155-1</a>	NO						
<a href="#">1-962915-3</a>	NO						
<a href="#">1-964294-3</a>	NO						
<a href="#">1-964300-3</a>	NO						
<a href="#">1-967240-1</a>	NO						
<a href="#">1-967623-6</a>	NO						
<a href="#">1-968849-2</a>	NO						
<a href="#">1241634-3</a>	NO						
<a href="#">1337352-1</a>	NO						
<a href="#">1355526-2</a>	NO						
<a href="#">1379118-1</a>	NO						
<a href="#">1379675-1</a>	NO						
<a href="#">1393280-5</a>	NO			"V23086C1001A402"			
<a href="#">1418884-3</a>	NO						
<a href="#">144969-2</a>	NO						
<a href="#">1544332-1</a>	NO			"P790861"			
<a href="#">1544333-1</a>	NO			"P790862"			
<a href="#">1563110-1</a>	NO						
<a href="#">166500-2</a>	NO						
<a href="#">1670364-1</a>	NO						
<a href="#">1670365-1</a>	NO						
<a href="#">172500-1</a>	NO						
<a href="#">183035-1</a>	NO			"CM8391-000", "AMP-0-0183035-1", "2-42939-6221", "820P-36547", "4004200209"			
<a href="#">2-1355123-3</a>	NO						
<a href="#">281934-3</a>	NO			"80.246.00"			
<a href="#">282080-2</a>	NO						
<a href="#">282107-1</a>	NO						
<a href="#">282189-1</a>	NO			"CF0543-000", "AMP-0-0282189-1"			
<a href="#">282308-1</a>	NO						
<a href="#">282466-1</a>	NO			"EG9735-000", "AMP-0-0282466-1"			
<a href="#">3-1418390-1</a>	NO						
<a href="#">344009-1</a>	NO						
<a href="#">345809-1</a>	NO						
<a href="#">6-968974-1</a>	NO						
<a href="#">7-1414967-8</a>	NO			"V23086-R1802-A803"			
<a href="#">7-1452671-3</a>	NO						
<a href="#">828801-4</a>	NO						
<a href="#">828801-5</a>	NO						
<a href="#">880811-2</a>	NO			"EG9729-000", "AMP-0-0880811-2", "51.033.00"			
<a href="#">9-1452380-9</a>	NO						
<a href="#">9-1563172-9</a>	NO						
<a href="#">9-1563173-9</a>	NO						
<a href="#">9-965382-2</a>	NO						
<a href="#">925590-2</a>	NO			"0-0925590-2"			
<a href="#">927768-9</a>	NO						
<a href="#">929387-1</a>	NO						
<a href="#">929504-1</a>	NO						
<a href="#">929504-2</a>	NO						
<a href="#">929504-3</a>	NO						
<a href="#">929504-4</a>	NO						
<a href="#">929504-5</a>	NO						
<a href="#">929504-6</a>	NO						
<a href="#">929650-2</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">929968-1</a>	NO						
<a href="#">929971-1</a>	NO						
<a href="#">929989-1</a>	NO						
<a href="#">929990-1</a>	NO						
<a href="#">963216-1</a>	NO						
<a href="#">963774-1</a>	NO						
<a href="#">963904-3</a>	NO						
<a href="#">965601-2</a>	NO						
<a href="#">967598-1</a>	NO						
<a href="#">968271-1</a>	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">7-1414967-8</a>	NO			"V23086-R1802-A803"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1355154-1</a>	NO						
<a href="#">1-1418448-1</a>	NO			"8202607143"			
<a href="#">1-1418479-1</a>	NO						
<a href="#">1-1418480-1</a>	NO						
<a href="#">1-1418775-1</a>	NO						
<a href="#">1-1534155-1</a>	NO						
<a href="#">1-1719506-3</a>	NO						
<a href="#">1-962915-3</a>	NO						
<a href="#">1-964294-3</a>	NO						
<a href="#">1-964300-3</a>	NO						
<a href="#">1-967240-1</a>	NO						
<a href="#">1-967623-6</a>	NO						
<a href="#">1-968849-2</a>	NO						
<a href="#">1241634-3</a>	NO						
<a href="#">1337352-1</a>	NO						
<a href="#">1355526-2</a>	NO						
<a href="#">1379118-1</a>	NO						
<a href="#">1379675-1</a>	NO						
<a href="#">1393280-5</a>	NO			"V23086C1001A402"			
<a href="#">1418884-3</a>	NO						
<a href="#">144969-2</a>	NO						
<a href="#">1544332-1</a>	NO			"P790861"			
<a href="#">1544333-1</a>	NO			"P790862"			
<a href="#">1563110-1</a>	NO						
<a href="#">166500-2</a>	NO						
<a href="#">1670364-1</a>	NO						
<a href="#">1670365-1</a>	NO						
<a href="#">172500-1</a>	NO						
<a href="#">183035-1</a>	NO			"CM8391-000", "AMP-0-0183035-1", "2-42939-6221", "820P-36547", "4004200209"			
<a href="#">2-1355123-3</a>	NO						
<a href="#">281934-3</a>	NO			"80.246.00"			
<a href="#">282080-2</a>	NO						



Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">282107-1</a>	NO						
<a href="#">282189-1</a>	NO			"CF0543-000", "AMP-0-0282189-1"			
<a href="#">282308-1</a>	NO						
<a href="#">282466-1</a>	NO			"EG9735-000", "AMP-0-0282466-1"			
<a href="#">3-1418390-1</a>	NO						
<a href="#">344009-1</a>	NO						
<a href="#">345809-1</a>	NO						
<a href="#">6-968974-1</a>	NO						
<a href="#">7-1414967-8</a>	NO			"V23086-R1802-A803"			
<a href="#">7-1452671-3</a>	NO						
<a href="#">828801-4</a>	NO						
<a href="#">828801-5</a>	NO						
<a href="#">880811-2</a>	NO			"EG9729-000", "AMP-0-0880811-2", "51.033.00"			
<a href="#">9-1452380-9</a>	NO						
<a href="#">9-1563172-9</a>	NO						
<a href="#">9-1563173-9</a>	NO						
<a href="#">9-965382-2</a>	NO						
<a href="#">925590-2</a>	NO			"0-0925590-2"			
<a href="#">927768-9</a>	NO						
<a href="#">929027-3</a>	NO						
<a href="#">929387-1</a>	NO						
<a href="#">929504-1</a>	NO						
<a href="#">929504-2</a>	NO						
<a href="#">929504-3</a>	NO						
<a href="#">929504-4</a>	NO						
<a href="#">929504-5</a>	NO						
<a href="#">929504-6</a>	NO						
<a href="#">929650-2</a>	NO						
<a href="#">929968-1</a>	NO						
<a href="#">929971-1</a>	NO						
<a href="#">929989-1</a>	NO						
<a href="#">929990-1</a>	NO						
<a href="#">963216-1</a>	NO						
<a href="#">963774-1</a>	NO						
<a href="#">963904-3</a>	NO						
<a href="#">965601-2</a>	NO						
<a href="#">967598-1</a>	NO						
<a href="#">968271-1</a>	NO						