

## **Change Notice Form**

Change Notice #	Date of Notice	Distribution:	🛛 General	Customer Specific
PCN 067	6/02/2022	Post Change Not	ice to Website	? 🛛 yes 🗌 no

Title:End of Life of AT25QF641 including Known Good Die and package options

Products Affected: See Appendix I for a list of complete part numbers.

Change Type:	
Document only Mat'l/Composition Manufacturing Process	
Manufacturing Location Quality/Reliability Dogistics	🗌 Design
🛛 EOL/Product Discontinuance 🗌 Other	

Qualification Report Available:	Click here to enter a date.	not applicable
Product Sample:	Click here to enter a date.	not applicable
Target Production Release:	Click here to enter a date.	

Last Time Buy:	Click here to enter a date.	🔀 not applicable
Last Time Ship Date:	Click here to enter a date.	🔀 not applicable

Sites Affected:	🛛 None	Description:		
Impact on Quality and Reliability	🛛 None	Description:		
Traceability of Change	🗌 not a	pplicable	🛛 Product Mark	Date Code
	Lot number traceability			

This change affects dat	asheet, form, fit,	function or	reliability of the product
	🛛 Yes	No No	🗌 Not Applicable



Description of Change: End of Life of all packages and Known Good Die and package options for AT25QF641. The AT25QF641, 64Mbit serial flash with all the options available have been moved to End of Life. The next generatrion AT25QF641B is available for existing design conversions and for all new designs. A 64Mbit conversion guide AN400 is available on our website. Note: A Technical note TN 111 for AT25QF641 is also available on our website describing the effects of excessive use of CS toggle operations.

Should you have any questions, please contact your local Renesas sales office or authorized distributor.

Renesas will deem this change accepted, unless specific written conditions of acceptance are provided by the customer, within 30 days from the date of this notice. Renesas reserves the right to ship either the original version or the new version of the affected product after the Target Production Release Date specified in this notice.

## **APPENDIX I Affected Products (insert here)**

Renesas Part Number	Replacement
AT25QF641-SUB-T	AT25QF641B-SHB-T
AT25QF641-DWF	AT25QF641B-DWF