



Cypress Semiconductor Corporation, 198 Champion Court, San Jose, CA 95134. Tel: (408) 943-2600

PRODUCT TERMINATION NOTIFICATION

PTN: PTN163704

Date: September 17, 2016

Subject: October 2016 Product Obsolescence Notification

To: JAMIE PEDERSON
DIGIKEY
digiKey.supplierInfo@digikey.com

Product Obsolescence Information:

Cypress announces the obsolescence of select products from its portfolio resulting from an internal review and business decision to discontinue support. The affected part numbers are listed in the attached table. Last Time Buy (LTB) and Last Time Ship (LTS) dates are provided for each product. The LTB date denotes the last day on which orders will be accepted; these orders may be scheduled for shipment through the LTS date provided.

Affected parts identified with Note 1 (Bluetooth) were setup in error and promulgated with transition from former Broadcom to Cypress. These parts are being obsoleted effective immediately. Actual part numbers that are equivalent to the former Broadcom part numbers are provided as drop in replacements.

The part listed as the "Drop-In Replacement" will perform the same task but with improved or revised technology. The part listed as the "Next Best Alternative" is the recommended replacement that may have some features or functions that are different and may require board re-design.

Affected Part Numbers: 453

Please see the attached file for a list of part numbers, Last Time Buy Dates and Last Time Ship Dates.

Qualification Status:

Recommended replacement parts have been previously qualified, unless specifically noted.

Sample Status:

Samples of replacement parts are available. Please contact your local sales representative to place sample orders.

Approximate Implementation Date:

This change is effective with this notification.

Response Required:

No response required. For additional information regarding this notice, contact the personnel listed in the table below, your local sales representative, or the PCN Administrator at pcn_adm@cypress.com.

Contact	Country	Phone Number	Email	Family of Parts
Jeff Kasper	US	408-239-9071	jeph@cypress.com	Bluetooth
Amy Chen	China	+8613701833290	amyc@cypress.com	MCU

Sincerely,

Cypress PCN Administration

Item	Marketing Part Number	Item Catalog Category	Last Time Buy (LTB)	Last Time Ship (LTS)	Drop In Replacement	Next Best Alternative	Notes
1	MB89935BPFV-G-117-BND-ER	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
2	MB89935BPFV-G-221-BND-ER	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
3	MB89135LPM-G-638-TLE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F698KPMC-G-SNE2	
4	MB89535AP-G-521-SHE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC-G-UNE2	
5	MB90574CPFV-G-453E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
6	MB90574CPFV-G-462E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
7	MB90574CPFV-G-449E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
8	MB9AF003ABGL-GE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
9	MB89123APMC-G-600-JNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F698KPMC-G-SNE2	
10	MB89123APFM-G-600-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F698KPMC-G-SNE2	
11	MB89935DPFV-GS-109-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
12	MB89636RPF-G-1437-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
13	MB89935DPFV-GS-115-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
14	MB90467PF-G-240E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF112LAPMC-G-JNE2	
15	MB89935DPFV-GS-112-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
16	MB89935DPFV-GS-107-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
17	MB89935DPFV-GS-104-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
18	MB9AF005PMC-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF005PMC-G-UNE2	
19	MB89615RPFM-G-1025-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
20	MB89615RPFM-G-1083-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
21	MB89935DPFV-GS-117-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
22	MB89935DPFV-GS-105-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
23	MB9AF009ABGL-GE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
24	MB95F398KPMC1-G-104-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F698KPMC1-G-UNE2	
25	MB9AF009BBGL-GE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
26	MB90467PF-G-254E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF112LAPMC-G-JNE2	
27	MB90574CPFV-G-456E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
28	MB95F263KPF-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F564KPF-G-UNE2	
29	MB9AF007PMC-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF007PMC-G-UNE2	
30	MB95F264KAPFT-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F564KAPFT-G-SNE2	
31	MB95005ABGL-G-132-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
32	MB95F398KPMC1-G-107-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F698KPMC1-G-UNE2	
33	MB95F263KPF-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F564KPF-G-UNE2	
34	MB90F574APFV-GE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
35	MB95F378EPMC1-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778EPMC1-G-SNE2	
36	MB9AF007PMC1-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF1A2LPMC1-G-SNE2	
37	MB9AF004BGL-G-K1ERE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
38	MB89195PF-G-636-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
39	MB95F282KPF-G-SNK4E1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F564KPF-G-UNE2	
40	MB89191APF-G-120-BND-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
41	MB90467PF-G-206E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF112LAPMC-G-JNE2	
42	MB9AF004BGL-G-105-K1ERE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
43	MB95F108ATSPMC-GE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC-G-UNE2	
44	MB95108AHPFV-G-115E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
45	MB89193PF-G-635-ER-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
46	MB95F136NSPF-GE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
47	MB89537APF-G-671E1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC-G-UNE2	
48	MB89193PF-G-559-ER-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
49	MB89193PF-G-601-ER-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
50	MB89193PF-G-541-ER-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
51	MB89193PF-G-569-ER-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
52	MB89193PF-G-655-ER-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
53	MB89485LAPFM-G-227-CNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778MPMC1-G-SNE2	
54	MB89485LAPFM-G-260-CNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778MPMC1-G-SNE2	
55	MB89193PF-G-612-ER-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
56	MB95F264KPF-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F564KPF-G-UNE2	
57	MB89485PFM-G-252-CNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778MPMC1-G-SNE2	
58	MB95128MBPF-G-106E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
59	MB89983PFM-G-195-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC-G-UNE2	
60	MB95F354LPFT-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F654LPF-G-UNE2	
61	MB95F223KPF-G-SNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F563KPF-G-SNE2	
62	MB90F462AP-G-SHE1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF112LAPMC-G-JNE2	
63	MB95F128MBPF-GE1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF008LWPMC-G-UNE2	
64	MB95F334KPMC-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
65	MB9AF008LWPMC-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF008LWPMC-G-UNE2	
66	MB89F202RAP-G-SH-SNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
67	MB89191APF-G-294-ER-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
68	MB9AF0A1MPW-G-110-AWERE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
69	MB89538APF-G-558-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC-G-UNE2	
70	MB90099PFV-G-147-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
71	MB89485PFM-G-182-CNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778MPMC1-G-SNE2	
72	MB90467PFM-G-297E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF112LAPMC-G-JNE2	
73	MB89485LAPFM-G-224-CNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778MPMC1-G-SNE2	
74	MB90562APMC-G-455-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF112LAPMC-G-JNE2	
75	MB9AF004BGL-G-103-K1ERE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
76	MB95F396KPMC1-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F696KPMC1-G-UNE2	
77	MB95F128MBPF-G-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF008LWPMC-G-UNE2	
78	MB95F128BPF-GSE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
79	MB95F264HPFT-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F564KPF-G-UNE2	
80	MB89485PFM-G-235-CNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778MPMC1-G-SNE2	
81	MB95F136KSPF-GE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
82	MB89163PFV-G-331-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718MPMC-G-SNE2	
83	MB89191APF-G-608-ER-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
84	MB90562APMC-G-460-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF112LAPMC-G-JNE2	
85	MB90562APMC-G-274-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF112LAPMC-G-JNE2	
86	MB89538APF-G-649E1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC-G-UNE2	

87	MB95F318E-CHIP	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718E-UJ-CHIP32	
88	MB90467PFM-G-281E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF112LAPMC-G-JNE2	
89	MB90562APMC-G-459-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF112LAPMC-G-JNE2	
90	MB90562APMC-G-458-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF112LAPMC-G-JNE2	
91	MB90562APMC-G-457-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF112LAPMC-G-JNE2	
92	MB89193PF-G-538-ER-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
93	MB95F212KPF-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F562KPF-G-SNE2	
94	MB95F282KPF-G-SNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F564KPF-G-UNE2	
95	MB89485LA-G-211-CHIP-CN	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718E-UJ-CHIP32	
96	MB89485LA-G-172-CHIP-CN	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718E-UJ-CHIP32	
97	MB89215-G-104-CHIP	MM MCU	5-Apr-17	2-Oct-17	None	None	
98	MB95F398KPMC1-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F698KPMC1-G-UNE2	
99	MB89F202AP-G-SH-SNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
100	MB95F118NSPMC-G-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F698KPMC1-G-UNE2	
101	MB95F354EPF-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F654EPF-G-SNE2	
102	MB95F334KP-G-SH-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
103	MB89485PFM-G-237-CNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778MPMC1-G-SNE2	
104	MB89485PFM-G-199-CNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778MPMC1-G-SNE2	
105	MB89485PFM-G-244-CNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778MPMC1-G-SNE2	
106	MB89485PFM-G-245-CNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778MPMC1-G-SNE2	
107	MB95F118BWPMT-G-SNE1	MM MCU	5-Apr-17	2-Oct-17	None	S6E1C11COAGV20000	
108	MB89485-G-262-CHIP-CN	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718E-UJ-CHIP32	
109	MB95F108AJSPMC-GE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC-G-UNE2	
110	MB89485-G-261-CHIP-CN	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718E-UJ-CHIP32	
111	MB95F478KPMC1-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778EPMC1-G-UNE2	
112	MB95F478KPMC2-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778EPMC2-G-UNE2	
113	MB95F478HPMC1-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778EPMC1-G-UNE2	
114	MB89485-G-263-CHIP-CN	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718E-UJ-CHIP32	
115	MB89P857P-G-SHE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
116	MB95F128BPFR-GE1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AFAA2NPMC-G-UNE2	
117	MB90F334APMC-G-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	S6E1B34G0AGV20000	
118	MB86C61BGL-G-DLE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
119	MB90F463APMC-G-SNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF112LAPMC-G-JNE2	
120	MB89935BPFV-G-210-BND-ER	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
121	MB89935BPFV-G-175-BND-ER	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
122	MB90673PF-G-286-BND-B	MM MCU	5-Apr-17	2-Oct-17	None	None	
123	MB90673PF-G-269-BND-B	MM MCU	5-Apr-17	2-Oct-17	None	None	
124	MB90673PF-G-310-BND-B	MM MCU	5-Apr-17	2-Oct-17	None	None	
125	MB89625RP-G-1103-SHE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
126	MB89625RP-G-1074-SHE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
127	MB89165PFV-G-299-BND-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718MPMC-G-SNE2	
128	MB89165PFV-G-297-BND-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718MPMC-G-SNE2	
129	MB89P165-103PFV-G	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718MPMC-G-SNE2	
130	MB89713APF-G-617-BND-TN	MM MCU	5-Apr-17	2-Oct-17	None	None	
131	MB89193APF-G-387-BND-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
132	MB89625RP-G-1072-SHE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
133	MB89567APFV-GS-242-BND	MM MCU	5-Apr-17	2-Oct-17	None	None	
134	MB89935BPFV-G-196-BND-ER	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
135	MB89165PFV-G-386-BND-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718MPMC-G-SNE2	
136	MB89193APF-G-443-BND-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
137	MB89P625P-G-SH-L	MM MCU	5-Apr-17	2-Oct-17	None	None	
138	MB89193PF-G-401-BND-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
139	MB89935BPFV-G-229-BND-ER	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
140	MB90467PFM-G-258E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF112LAPMC-G-JNE2	
141	MB90467PFM-G-256E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF112LAPMC-G-JNE2	
142	MB89P935APFV-G	MM MCU	5-Apr-17	2-Oct-17	None	None	
143	MB89537APF-G-658E1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC-G-UNE2	
144	MB89615RPFM-G-606-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
145	MB89626RPF-G-1065-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
146	MB89935BPFV-G-197-BND-ER	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
147	MB89193PF-G-326-BND-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
148	MB95F203KPF-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F564KPF-G-UNE2	
149	MB90678PF-G-239-BND-B	MM MCU	5-Apr-17	2-Oct-17	None	None	
150	MB89193PF-G-412-BND-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
151	MB89123APFM-G-457-BND	MM MCU	5-Apr-17	2-Oct-17	None	MB95F698KPMC-G-SNE2	
152	MB89163PFV-G-218-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718MPMC-G-SNE2	
153	MB90467PF-G-174E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF112LAPMC-G-JNE2	
154	MB90467PFM-G-282E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF112LAPMC-G-JNE2	
155	MB89626RPFM-G-698-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
156	MB89935BPFV-G-312-ER	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
157	MB90467PF-G-172E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF112LAPMC-G-JNE2	
158	MB89935BPFV-G-152-BND-ER	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
159	MB89567APFV-GS-248	MM MCU	5-Apr-17	2-Oct-17	None	None	
160	MB89935BPFV-G-201-BND-ER	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
161	MB89615RPFM-G-1108-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
162	MB89627RPF-G-1064-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
163	MB89626RPFM-G-1106-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
164	MB89537APF-G-656E1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC-G-UNE2	
165	MB95106AHPFM-G-120E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
166	MB89935BPFV-G-173-BND-ER	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
167	MB89935BPFV-G-184-BND-ER	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
168	MB89935BPFV-GS-383-EFE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
169	MB89935BPFV-GS-385-EFE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
170	MB95F118NWPMT-G-GE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F698KPMC1-G-UNE2	
171	MB89935BPFV-G-266-BND-ER	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
172	MB89613RPMC-G-685E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
173	MB90574CPFV-G-448E1	MM MCU	5-Apr-17	2-Oct-17	None	None	

174	MB89626RPFM-G-1079-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
175	MB89535AP-G-1032-SHE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC-G-UNE2	
176	MB88111PF-GT-BND	MM MCU	5-Apr-17	2-Oct-17	None	None	
177	MB89485PFM-G-247-CNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778MPMC1-G-SNE2	
178	MB89535AP-G-1123-SHE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC-G-UNE2	
179	MB89567APMC1-G-343E1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718JPMC-G-SNE2	
180	MB89193PF-G-652-ER-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
181	MB89133APFM-G-691TLE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F698KPMC-G-SNE2	
182	MB89935BPFV-G-219-ER	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
183	MB89485LAPFM-G-236-CNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778MPMC1-G-SNE2	
184	MB89475PFM-G-123E1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F698KPMC-G-SNE2	
185	MB95F272KPF-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F562KPF-G-SNE2	
186	MB89485LA-G-217-CHIP-CN	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718E-UJ-CHIP32	
187	MB89983PMC-G-145-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC-G-UNE2	
188	MB89485PFM-G-216-CNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778MPMC1-G-SNE2	
189	MB90F831PF-G-SPE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
190	MB95F398KPMC1-G-105-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F698KPMC1-G-XXX-UNE2	
191	MB89135LPFM-G-649-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F698KPMC-G-SNE2	
192	MB89485-G-212-CHIP-CN	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718E-UJ-CHIP32	
193	MB89485-G-218-CHIP-CN	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718E-UJ-CHIP32	
194	MB95F354EPFT-G-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F654EPFT-G-UNE2	
195	MB89485-G-204-CHIP-CN	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718E-UJ-CHIP32	
196	MB95F108AHWP1MC1-GN9E1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC1-G-UNE2	
197	MB95F108AKSP1MC1-GS-N2E1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC1-G-UNE2	
198	MB91F482PMC-G-N2E1	MM MCU	5-Apr-17	2-Oct-17	None	S6E2H14G0AGV20000	
199	MB91F482PMC-G-N9E1	MM MCU	5-Apr-17	2-Oct-17	None	S6E2H14G0AGV20000	
200	MB91F487PMC-G-N2E1	MM MCU	5-Apr-17	2-Oct-17	None	S6E2H16G0AGV20000	
201	MB91F627PMC-G-N9E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF156NAPMC-G-UNE2	
202	MB89191APF-G-491-BND-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
203	MB89193PF-G-XXX-ER-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
204	MB89191APF-G-575-ER-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
205	MB89191APF-G-576-ER-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
206	MB89191APF-G-XXX-ER-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
207	MB89193PF-G-611-ER-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
208	MB89191PF-G-572-ER-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
209	MB89935BPFV-G-270-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
210	MB89935BPFV-G-368-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
211	MB89935BPFV-G-236-BND-ER	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
212	MB89935BPFV-G-361-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
213	MB89935BPFV-G-398-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
214	MB89935BPFV-G-325-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
215	MB89935BPFV-G-375-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
216	MB89935BPFV-G-337-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
217	MB89193PF-G-396-BND-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
218	MB89191APF-G-657-ER-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
219	MB89193APF-G-201-BND-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
220	MB89193APF-G-210-BND-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
221	MB89193APF-G-219-BND-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
222	MB89193APF-G-237-BND-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
223	MB89193APF-G-261-BND-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
224	MB89193APF-G-262-BND-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
225	MB89193APF-G-267-BND-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
226	MB89193APF-G-298-BND-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
227	MB89193APF-G-345-BND-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
228	MB89193APF-G-346-BND-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
229	MB89193APF-G-450-BND-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
230	MB89193APF-G-454-BND-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
231	MB89193APF-G-456-BND-R	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
232	MB89193PF-G-317-BND-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
233	MB89193PF-G-596-ER-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
234	MB89191PF-G-331-ER-RE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
235	MB89535APF-G-1075E1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC-G-UNE2	
236	MB89538APFM-G-1047	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC-G-UNE2	
237	MB89537APF-G-1126E1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC-G-UNE2	
238	MB89538APF-G-1128E1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC-G-UNE2	
239	MB89537APFM-G-613-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC-G-UNE2	
240	MB89538APFM-G-1124E1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC-G-UNE2	
241	MB89538APMC-G-702-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC-G-UNE2	
242	MB89485PFM-G-255-CNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778MPMC1-G-SNE2	
243	MB89183PMC3-G-XXX-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC1-G-SNE2	
244	MB89567A-G-333-CHIP	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718JPMC-G-SNE2	
245	MB89567APMC1-G-334E1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718JPMC-G-SNE2	
246	MB89183PMC3-G-319-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC1-G-SNE2	
247	MB89567APF-G-181-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718JPMC-G-SNE2	
248	MB89133APFM-G-471-TLE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F698KPMC-G-SNE2	
249	MB89183PMC-G-332-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F818KPMC1-G-SNE2	
250	MB89485PFM-G-XXX-CNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778MPMC1-G-SNE2	
251	MB89567APF-G-197-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718JPMC-G-SNE2	
252	MB89567APFV-GS-243-BND	MM MCU	5-Apr-17	2-Oct-17	None	MB95F718JPMC-G-SNE2	
253	MB90523BPMC1-G-191E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AFAA2NPMC-G-SNE2	
254	MB90523BPMC1-G-188E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AFAA2NPMC-G-SNE2	
255	MB90438LSPMC-G-XXXE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
256	MB89983L-G-233-CHIP	MM MCU	5-Apr-17	2-Oct-17	None	None	
257	MB89985L-G-215-CHIP	MM MCU	5-Apr-17	2-Oct-17	None	None	
258	MB89935DPFV-GS-111-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
259	MB89985L-G-232-CHIP	MM MCU	5-Apr-17	2-Oct-17	None	None	
260	MB95010PMC-G-123E1	MM MCU	5-Apr-17	2-Oct-17	None	None	

261	MB95010PMC-G-126E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
262	MB90438LSPFV-G-XXX-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
263	MB90462PFM-G-XXX-SNE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
264	MB90467PFM-G-XXX-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
265	MB95004APMT-G-144E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
266	MB95004APMT-G-145E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
267	MB90553BPMC-G-XXX-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
268	MB90574CPMT-G-446E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
269	MB90823BPMC1-G-XXXE1	MM MCU	5-Apr-17	2-Oct-17	None	None	MB9BF122MPMC1-G-JNE2
270	MB89935DPFV-GS-113-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
271	MB90F562BPFM-GE1	MM MCU	5-Apr-17	2-Oct-17	None	None	MB9AF112LAPMC-G-JNE2
272	MB86687APFV-G-BND	MM MCU	5-Apr-17	2-Oct-17	None	None	
273	MB95005ABGL-G-137-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
274	MB88346BPF-G-JN-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
275	MB88346LPFV-G-BND-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
276	MB89935DPFV-GS-106-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
277	MB89935BPFV-GS-314-EFE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
278	MB89935BPFV-GS-403-EFE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
279	MB89615RPMC-G-1090-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
280	MB89637RP-G-1387-SH	MM MCU	5-Apr-17	2-Oct-17	None	None	
281	MB89657ARPF-G-292-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
282	MB89635RPMC-G-204-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
283	MB89935BPFV-GS-XXX-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
284	MB90462PFM-G-312-SNE1	MM MCU	5-Apr-17	2-Oct-17	None	None	MB9AF112LAPMC-G-JNE2
285	MB90462PFM-G-326-SNE1	MM MCU	5-Apr-17	2-Oct-17	None	None	MB9AF112LAPMC-G-JNE2
286	MB90096PF-G-244-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
287	MB90467PF-G-XXXE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
288	MB90552BPF-G-345-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
289	MB90553BPMC-G-357-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
290	MB90673PF-GT-291-BND-BE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
291	MB90673PF-GT-318-BND-BE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
292	MB90673PF-GT-320-BND-BE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
293	MB90673PF-GT-321-BND-BE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
294	MB90673PF-GT-357-BND-BE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
295	MB90673PF-GT-362-BND-BE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
296	MB90673PF-GT-379-BND-BE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
297	MB90467PFM-G-308-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	None	MB9AF112LAPMC-G-JNE2
298	MB90822PMC1-G-132E1	MM MCU	5-Apr-17	2-Oct-17	None	None	MB9BF122MPMC1-G-JNE2
299	MB90F462PMC-GE1	MM MCU	5-Apr-17	2-Oct-17	None	None	MB9AF112LAPMC-G-JNE2
300	MB90762HPMC-G-155-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
301	MB90467PF-G-272E1	MM MCU	5-Apr-17	2-Oct-17	None	None	MB9AF112LAPMC-G-JNE2
302	MB89601RPMC-G-167-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
303	MB91661PMC-G-XXXE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
304	MB91F036PFF-GE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
305	MB90462PFM-G-245-SNE1	MM MCU	5-Apr-17	2-Oct-17	None	None	MB9AF112LAPMC-G-JNE2
306	MB91F668PMC-G-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	None	S6E1B36G0AGV20000
307	MB96345RSAPMC-GS-XXXE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
308	MB88515PF-GT-317H-BND	MM MCU	5-Apr-17	2-Oct-17	None	None	
309	MB88572P-GT-319M-SH	MM MCU	5-Apr-17	2-Oct-17	None	None	
310	MB89053PF-G-138-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
311	MB89623RPF-G-360-TLE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
312	MB89374-PFQ-G-BND	MM MCU	5-Apr-17	2-Oct-17	None	None	
313	MB90462PFM-G-293-SNE1	MM MCU	5-Apr-17	2-Oct-17	None	None	MB9AF112LAPMC-G-JNE2
314	MB89615RPFM-G-1003-BND	MM MCU	5-Apr-17	2-Oct-17	None	None	
315	MB89615RPFM-G-652-BND	MM MCU	5-Apr-17	2-Oct-17	None	None	
316	MB89615RPFM-G-653-BND	MM MCU	5-Apr-17	2-Oct-17	None	None	
317	MB89623P-GT-125-SHE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
318	MB90F049APMC-G-109E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
319	MB89623RPF-G-407-TLE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
320	MB89635RPF-G-1128-BND	MM MCU	5-Apr-17	2-Oct-17	None	None	
321	MB89635RPF-G-XXXE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
322	MB89637P-GT-655-SH	MM MCU	5-Apr-17	2-Oct-17	None	None	
323	MB89655ARPMC-G-410E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
324	MB89657ARPF-G-347-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
325	MB89697BPFM-G-316	MM MCU	5-Apr-17	2-Oct-17	None	None	
326	MB89713APF-G-380-BND-TN	MM MCU	5-Apr-17	2-Oct-17	None	None	
327	MB89713APF-G-458-BND-TN	MM MCU	5-Apr-17	2-Oct-17	None	None	
328	MB89713APF-G-526-BND-TN	MM MCU	5-Apr-17	2-Oct-17	None	None	
329	MB89713APF-G-555-BND-TN	MM MCU	5-Apr-17	2-Oct-17	None	None	
330	MB89713APF-G-565-BND-TN	MM MCU	5-Apr-17	2-Oct-17	None	None	
331	MB89713APF-G-598-BND-TN	MM MCU	5-Apr-17	2-Oct-17	None	None	
332	MB89715APF-G-549-BND-TN	MM MCU	5-Apr-17	2-Oct-17	None	None	
333	MB89715APF-G-562-BND-TN	MM MCU	5-Apr-17	2-Oct-17	None	None	
334	MB89715APF-G-566-BND-TN	MM MCU	5-Apr-17	2-Oct-17	None	None	
335	MB89715APF-G-599-BND-TN	MM MCU	5-Apr-17	2-Oct-17	None	None	
336	MB89715APF-G-602-TN-TK2	MM MCU	5-Apr-17	2-Oct-17	None	None	
337	MB89715APF-G-613-BND-TN	MM MCU	5-Apr-17	2-Oct-17	None	None	
338	MB89715APF-G-614-BND-TN	MM MCU	5-Apr-17	2-Oct-17	None	None	
339	MB89715APF-G-618-BND-TN	MM MCU	5-Apr-17	2-Oct-17	None	None	
340	MB89715APF-G-620-BND-TN	MM MCU	5-Apr-17	2-Oct-17	None	None	
341	MB89888P-G-177-SHE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
342	MB89925PF-G-148-BNDE1	Auto MCU	5-Jul-17	1-Jan-18	None	None	
343	MB89925PF-G-234E1	Auto MCU	5-Jul-17	1-Jan-18	None	None	
344	MB91661PMC-G-110-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	None	S6E1B36G0AGV20000
345	MB89935BPFV-GS-277-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
346	MB89855RPF-G-204-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
347	MB89P475-101PMC-GSE1	MM MCU	5-Apr-17	2-Oct-17	None	None	

348	MB90548GSPMC-G-196-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
349	MB89P625PMC-G-LE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
350	MB90088PF-G-123-BND	MM MCU	5-Apr-17	2-Oct-17	None	None	
351	MB90096PF-G-257-BND	MM MCU	5-Apr-17	2-Oct-17	None	None	
352	MB90096PF-G-263E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
353	MB90347DASPFV-GS-445E1	Auto MCU	5-Jul-17	1-Jan-18	None	None	
354	MB90349CASPFV-GS-644E1	Auto MCU	5-Jul-17	1-Jan-18	None	None	
355	MB90438LSPMC-G-469E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
356	MB90F884APMC-G-106-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF144NBPMC-G-JNE2	
357	MB95005ABGL-G-129-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
358	MB91486PMC-G-103E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
359	MB95008APMC-G-117E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
360	MB95008APMC-G-XXXE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
361	MB90462PFM-G-277E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF112LAPMC-G-JNE2	
362	MB95010PMC-G-108E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
363	MB95108HPPFM-G-XXX-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
364	MB89653ARPF-G-348-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
365	MB91661PMC-G-106E1	MM MCU	5-Apr-17	2-Oct-17	None	S6E1B36G0AGV20000	
366	MB95136MBPFV-GS-110-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
367	MB90762PF-G-126-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
368	MB89P185-105PF-GE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
369	MB90673PF-GT-350-BND-BE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
370	MB91195ABGL-G-274-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
371	MB90553BAPF-GS-289-BND	MM MCU	5-Apr-17	2-Oct-17	None	None	
372	MB90561APMC-G-269-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF112LAPMC-G-JNE2	
373	MB90634APF-G-117-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
374	MB90671PF-G-324-BND-C	MM MCU	5-Apr-17	2-Oct-17	None	None	
375	MB90673PF-G-225-BND-B	MM MCU	5-Apr-17	2-Oct-17	None	None	
376	MB90673PF-G-347-BND-B	MM MCU	5-Apr-17	2-Oct-17	None	None	
377	MB90673PF-G-384-BND-B	MM MCU	5-Apr-17	2-Oct-17	None	None	
378	MB90673PF-GT-172-BND-B	MM MCU	5-Apr-17	2-Oct-17	None	None	
379	MB90673PF-GT-199-BND-B	MM MCU	5-Apr-17	2-Oct-17	None	None	
380	MB90673PF-GT-323-BND-BE1	Auto MCU	5-Jul-17	1-Jan-18	None	None	
381	MB90673PF-GT-342-BND-B	MM MCU	5-Apr-17	2-Oct-17	None	None	
382	MB95F118MSPMC-GE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F698KPMC1-G-UNE2	
383	MB91195ABGL-G-283-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
384	MB90678PF-G-221-BND-B	MM MCU	5-Apr-17	2-Oct-17	None	None	
385	MB95F166DPMC1-G-SPE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778EPMC1-G-UNE2	
386	MB95F398KPMC1-G-106-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F698KPMC1-G-UNE2	
387	MB90678PF-G-223-BND-B	MM MCU	5-Apr-17	2-Oct-17	None	None	
388	MB95F478HPMC2-G-108-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778LPMC2-G-UNE2	
389	MB90678PF-G-224-BND-B	MM MCU	5-Apr-17	2-Oct-17	None	None	
390	MB89673ARPF-G-228-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
391	MB90678PF-G-225-BND-B	MM MCU	5-Apr-17	2-Oct-17	None	None	
392	MB90678PF-G-249-BND-B	MM MCU	5-Apr-17	2-Oct-17	None	None	
393	MB95004APMT-G-XXXE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
394	MB90678PF-G-264-BND-B	MM MCU	5-Apr-17	2-Oct-17	None	None	
395	MB90333APMC-G-103-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	S6E1B34G0AGV20000	
396	MB90F334APMC-G-SPE1	MM MCU	5-Apr-17	2-Oct-17	None	S6E1B34G0AGV20000	
397	MB90F337PMC-GE1	MM MCU	5-Apr-17	2-Oct-17	None	MB9BF322LPMC-G-JNE2	
398	MB90F337PMC-G-N9E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9BF322LPMC-G-JNE2	
399	MB90F376PMC-G-90225PE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
400	MB90F375PFF-G-90195PE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
401	MB95010PMC-G-124E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
402	MB90F882ASPMC-G-N9E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF144NBPMC-G-JNE2	
403	MB95010PMC-G-125E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
404	MB90F882SPMC-G-N9E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF144NBPMC-G-JNE2	
405	MB91133PMC-G-123E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
406	MB90F883CSPMC-G-N2E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF144NBPMC-G-JNE2	
407	MB95108AHPMC1-GS-138E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
408	MB90F883CSPMC-G-N9E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF144NBPMC-G-JNE2	
409	MB95117MPMC-GS-XXXE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
410	MB90F884APMC-G-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF144NBPMC-G-JNE2	
411	MB90F884CPMC-GS-N2E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AF144NBPMC-G-JNE2	
412	MB90F9275PF-G-N2E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
413	MB90P263PF-G-5016-A-TK2	MM MCU	5-Apr-17	2-Oct-17	None	None	
414	MB95136MBPFV-GS-112E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
415	MB91101APFV-G-BNDE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
416	MB91213APMC-GS-102E1	Auto MCU	5-Jul-17	1-Jan-18	None	None	
417	MB91F264BPMC-G-101E1	MM MCU	5-Apr-17	2-Oct-17	None	S6E2H14G0AGV20000	
418	MB89P568-101PFV-GE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
419	MB95136MBPFV-GS-112-ERE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
420	MB91F128PMC-G-N9E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
421	MB95F010PMC-G-111E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
422	MB95F118JSPMCR-G-N9E1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F698KPMC-G-UNE2	
423	MB95F118MSPMC-G-N9E1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F698KPMC1-G-UNE2	
424	MB95F118MSPMC-G-N9-YE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F698KPMC1-G-UNE2	
425	MB91F196BGL1-GE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
426	MB91F211BPMC-GS-N2E1	Auto MCU	5-Jul-17	1-Jan-18	None	None	
427	MB91F264BPF-G-N9E1	MM MCU	5-Apr-17	2-Oct-17	None	S6E2H14G0AGV20000	
428	MB91F264BPF-G-N9K4E1	MM MCU	5-Apr-17	2-Oct-17	None	S6E2H14G0AGV20000	
429	MB91F264BPMC-G-N2E1	MM MCU	5-Apr-17	2-Oct-17	None	S6E2H14G0AGV20000	
430	MB91F353APMCR-G-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	S6E2H16G0AGV20000	
431	MB91F353APMT-G-N2E1	MM MCU	5-Apr-17	2-Oct-17	None	S6E2H16G0AGV20000	
432	MB91F475PMC1-G-N2E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9BF116SPMC-GE1	
433	MB95F128HPF-G-JNE1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AFAA2NPMC-G-UNE2	
434	MB91F479PMC1-G-N2E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9BF116SPMC-GE1	

435	MB91F479PMC1-G-N9-YE1	MM MCU	5-Apr-17	2-Oct-17	None	MB9BF116SPMC-GE1	
436	MB95F128JBPF-GS-N2E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
437	MB91F482PMC-G-N9-YE1	MM MCU	5-Apr-17	2-Oct-17	None	S6E2H14G0AGV20000	
438	MB95F128JBPMC-GS-N2E1	MM MCU	5-Apr-17	2-Oct-17	None	None	
439	MB95F128MBPF-G-N2E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AFAA2NPMC-G-UNE2	
440	MB95F128MBPF-G-N9E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AFAA2NPMC-G-UNE2	
441	MB91F639PMC-G-N2-YE1	MM MCU	5-Apr-17	2-Oct-17	None	MB9BF128SAPMC-GE1	
442	MB95F128MBPMC-G-N9E1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AFAA2NPMC-G-UNE2	
443	MB95F128MBPMC-G-N9-YE1	MM MCU	5-Apr-17	2-Oct-17	None	MB9AFAA2NPMC-G-UNE2	
444	MB95F134JBSPFV-GE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636KPMC-G-UNE2	
445	MB91F662PMC-G-N2E1	MM MCU	5-Apr-17	2-Oct-17	None	S6E1B36G0AGV20000	
446	MB91F662PMC-G-N9E1	MM MCU	5-Apr-17	2-Oct-17	None	S6E1B36G0AGV20000	
447	MB95F136MBSPFV-G-N2E1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636HPMC-G-UNE2	
448	MB95F136NBSPFV-GS-N2E1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F636HPMC-G-UNE2	
449	MB9G711DAPMC-GSE1	MM MCU	5-Apr-17	2-Oct-17	None	None	
450	MB95F334KWQN-G-SNERE1	MM MCU	5-Apr-17	2-Oct-17	None	MB95F634KWQN-G-UNERE2	
451	MB95F478HPMC2-G-113-SNE2	MM MCU	5-Apr-17	2-Oct-17	None	MB95F778LPMC2-G-XXX-UNE2	
452	BCM20732A1KML2G	Bluetooth, BLE and IEEE 802.15.4	19-Sep-16	19-Sep-16	BCM20736A1KML2G	None	Note 1
453	BCM20735KMLG	Bluetooth, BLE and IEEE 802.15.4	19-Sep-16	19-Sep-16	BCM20735PKML1G	None	Note 1

Note 1: parts were setup in error and promulgated with transition from former Broadcom to Cypress. These parts are being obsoleted effective immediately. Actual part numbers that are equivalent to the former Broadcom part numbers are