

Finisar® Transceiver

Date Issued: January 8th, 2021

End of Life Notification EOL20.040

300m SFP+ 10GBASE-SR/SW FTLX8573D3BTL variants

This document is an End of Life Notification (EOL) for I-temp version of 300m 10G SR SFP+ transceivers.

Affected Part Numbers and Recommended Replacement Part Numbers

The II-VI part numbers affected by this EOL notice are as follows:

II-VI EOL Part Number	Suggested Replacement
FTLX8573D3BTL	FTLX857 4 D3BTL
FTLX8573D3BTLxxx	FTLX857 4 D3BTLxxx

Reason for Discontinuation

We are running out of the existing VCSEL, and no replacement can be found that is compatible with the FTLX8573 platform.

End of Life Dates

No LTB would be provided for FTLX8573, but samples will be available approximately February 20, 2021 for FTLX8574D3BTL upon request.

We apologize in advance for any inconvenience this may cause. Please do not hesitate to call on your local distributor, rep, or local II-VI sales manager for any additional information you need.

For More Information please contact your local II-VI representative, or

II-VI Incorporated 375 Saxonburg Boulevard Saxonburg, PA 16056 photonics.sales@ii-vi.com www.ii-vi.com