



Product Change Notification / SYST-03SNJZ608

Date:

04-Aug-2020

Product Category:

USB Hubs

PCN Type:

Document Change

Notification Subject:

Data Sheet - USB5734 - 4-Port SS/HS USB Hub Controller - Data Sheet Document Revision

Affected CPNs:

[SYST-03SNJZ608_Affected_CPN_08042020.pdf](#)

[SYST-03SNJZ608_Affected_CPN_08042020.csv](#)

Notification Text:

SYST-03SNJZ608

Microchip has released a new Product Documents for the USB5734 - 4-Port SS/HS USB Hub Controller - Data Sheet of devices. If you are using one of these devices please read the document located at [USB5734 - 4-Port SS/HS USB Hub Controller - Data Sheet](#).

Notification Status: Final

Description of Change:

- 1) USB 3.1 changed to USB 3.2 throughout document.
- 2) Table 3-2, Pin Reset State Legend: Table added.
- 3) Pin Descriptions on page 10: Reset State column added to Pin Assignment table. Notes added to tables explaining what to do with certain pins when unused.
- 4) Section 10.2, Operating Conditions**: Supply Voltage Rise Time increased to 5ms.
- 5) Section FIGURE 10-1:, Supply Rise Time Model: Note added following diagram.

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 04 Aug 2020

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

[USB5734 - 4-Port SS/HS USB Hub Controller - Data Sheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

USB5734-I/MR

USB5734/MR

USB5734/MRD01

USB5734/MRD02

USB5734/MRTB

USB5734REL/MR

USB5734T-I/MR

USB5734T/MR

USB5734T/MRD01

USB5734T/MRD02